


Vehicle details

VIN	KMHK581GF KU053523	Brand	HYUNDAI	Maintenance date	-
Licence Plate	G7-47-PR	Model	KONA EV Premium 64 kWh	Maintenance mileage	-
Registration date	15/10/2019	Year	2019	Exterior Color	Red Metallic
Odometer	124 280 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	SUV CrossOver	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/12/2024	Inspection loc.	Koopman Car Terminal CN
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓






Tyres




Nexen 215/55/17 Summer 3.0 mm   Nexen 215/55/17 Summer 3.0 mm 

Nexen 215/55/17 Summer 5.0 mm   Nexen 215/55/17 Summer 5.0 mm

Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Upper tailgate / Boot</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Upper tailgate / Boot	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Door																						
Position	Back left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Upper tailgate / Boot																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Door																						
Position	Front right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair												
Part	Roof																						
Position	-																						
Damages	Dent & Chips																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						

Interior damage

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Broken	Severity	-	Repair mode	Replace
Part	Interior tailgate lining										
Position	-										
Damages	Broken										
Severity	-										
Repair mode	Replace										