



WBA6N31020FK87718

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	80,570 km
Manufacturer	BMW	Next maintenance in	18,000 km
Type / Model	330e	Main inspection (Report not on hand)	02/2026
Vehicle Identification number	WBA6N31020FK87718	Power / Engine displacement	135 kW / 1,998 ccm
First registration	26 Jan 2021	Upholstery/Colour	/
Last maintenance	10/2024, 73,762 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Main inspection certificate (Fehlt) - No deduction
2	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
3	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
4	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
5	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
6	Side panel - rear left side	Side panel - Scratch(es) - Cover / polish
7	Trim / covers	Trim / covers (Stift Fehlt Tür hi re.) - Un- / install
8	Mudguard - right side	Mudguard - right side - Dent(s) - Smooth repair work
9	Rear bumper	Rear bumper - Scratched - Smart repair
10	2nd wheel set	3 alloy rims - Scratched - Loss in value
11	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front left side	Door edge - Scratched - No deduction
2	Vehicle glazing	Windscreen (Steinschläge) - No deduction
3	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Rear, Provided by user / customer



Detected repainting

No.	Location
1	Mudguard - left side, Side panel - rear right side, Door - front left side, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R19 93Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	255/35 R19 96Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

Fahrzeug war zum Zeitpunkt der Besichtigung regennass, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Feb 2025

Protocol number: 38364846

Delivery date: 11 Feb 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	330e	Mileage (Read)	80,570 km
Vehicle Identification number	WBA6N31020FK87718	First registration	26 Jan 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was verified during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 11 Feb 2025
Protocol number: 38364846
Delivery date: 11 Feb 2025



Figure 25: Misc.

Pictures of damage



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction




Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #5: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #5: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #5: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #6: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Damage #6: Side panel - rear left side: Side panel - Scratch(... - Cover / polish



Damage #7: Trim / covers: Trim / covers (Stift Fehlt Tür hi re.) - Un- / install




Damage #7: Trim / covers: Trim / covers (Stift Fehlt Tür hi re.) - Un- / install




Damage #8: Mudguard - right side: Mudguard - right side - Dent(... Smooth repair work



Damage #8: Mudguard - right side: Mudguard - right side - Dent(s) - Smooth repair work



Damage #9: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #9: Rear bumper: Rear bumper - Scratched - Smart repair




Damage #9: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #10: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #10: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #10: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #10: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #11: Front bumper: Front bumper - Scratched - Rep... and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Feb 2025
Protocol number: 38364846
Delivery date: 11 Feb 2025



Auto Plus



Damage #11: Front bumper: Front bumper - Scratched - Repair a...
paint



Damage #11: Front bumper: Front bumper - Scratched - Rep...
and paint



Damage #11: Front bumper: Front bumper - Scratched - Repair a...
paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Feb 2025
Protocol number: 38364846
Delivery date: 11 Feb 2025



Auto Plus

Pictures of repainting



Repainting 1: Mudguard - left side, Side panel - rear right side,
Door - front left side