



WBA5P51020FK85100

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	96,896 km
Manufacturer	BMW	Next maintenance in	25,000 km
Type / Model	330e	Main inspection (Read from ZBI)	02/2026
Vehicle Identification number	WBA5P51020FK85100	Power / Engine displacement	135 kW / 1,998 ccm
First registration	2 Feb 2021	Upholstery/Colour	/
Last maintenance	12/2024, 91,259 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Vehicle glazing	Windscreen (Steinschläge) - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - Cover / polish
3	Bonnet	Bonnet - Scratch(es) - Conditioning
4	Front bumper	Front bumper - Scratched - Smart repair
5	2nd wheel set	Tyres - complete set (Sommer /innen + außen abgefahren) - Worn - Replace
6	Side panel - rear left side	Side panel - Scratch(es) - Paint
7	Side panel - rear right side	Side panel - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	7mm - 7mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 Mar 2025

Protocol number: 38942504

Delivery date: 20 Mar 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Hankook	Summer tyres	5mm - 5mm	o.k.	
2	225/50 R17 98Y	Hankook	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 Mar 2025

Protocol number: 38942504

Delivery date: 20 Mar 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e	Mileage (Read)	96,896 km
Vehicle Identification number	WBA5P51020FK85100	First registration	2 Feb 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.


Pictures of damage



Damage #2: Rear bumper: Rear bumper - Scratch(es) - Cover / polish



Damage #2: Rear bumper: Rear bumper - Scratch(es) - Cove... polish



Damage #3: Bonnet: Bonnet - Scratch(es) - Conditioning



Damage #3: Bonnet: Bonnet - Scratch(es) - Conditioning



Damage #4: Front bumper: Front bumper - Scratched - Smart repair




Damage #4: Front bumper: Front bumper - Scratched - Smart repair



Damage #5: 2nd wheel set: Tyres - complete set (Sommer /innen + außen abgefahren) - Worn - Replace



Damage #5: 2nd wheel set: Tyres - complete set (Sommer /innen + außen abgefahren) - Worn - Replace



Damage #6: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage #5: 2nd wheel set: Tyres - complete set (Sommer /innen + außen abgefahren) - Worn - Replace



Damage #5: 2nd wheel set: Tyres - complete set (Sommer /innen + außen abgefahren) - Worn - Replace




Damage #6: Side panel - rear left side: Side panel - Scratch(...) - Paint



Damage #7: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Damage #7: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Damage #7: Side panel - rear right side: Side panel - dent(s) - Repair and paint