



WAUZZZ8V2LA036527

Vehicle details

Operator		Inspection condition	conditional: sufficient
License number		Mileage (Read)	63,061 km
Manufacturer	Audi	Next maintenance in	13,000 km
Type / Model	A3 Sportback	Main inspection (Report on hand)	12/2026
Vehicle Identification number	WAUZZZ8V2LA036527	Power / Engine displacement	110 kW / 1,498 ccm
First registration	2 Dec 2019	Upholstery/Colour	/
Last maintenance	11/2023, 46,009 km	Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Roof	Roof rail - right side - Dent / paintcoat damage - Smooth repair work
3	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
4	Roof	Roof - dent(s) - Smooth repair work
5	2nd wheel set	Alloy rim set - complete - Scratched - Loss in value
6	Rear bumper	Rear bumper - Scratched - Repair and paint
7	Door - rear left side	Door - Scratched - Paint
8	Bonnet	Bonnet - Scratched - Paint
9	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38922373
Delivery date: 19 Mar 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91T	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	205/55 R16 91T	Goodyear	Winter tyres	7mm - 7mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R17 91Y	Bridgestone	Summer tyres	4mm - 4mm	o.k.	
2	225/45 R17 91Y	Bridgestone	Summer tyres	4mm - 4mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					10/2023

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38922373
Delivery date: 19 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: sufficient
Type / Model	A3 Sportback	Mileage (Read)	63,061 km
Vehicle Identification number	WAUZZZ8V2LA036527	First registration	2 Dec 2019

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were only partially sufficient for assessing the vehicle. At the time of the inspection, it could not be ensured that the condition was sufficient for an adequate assessment. The expert therefore recommends a further inspection to reduce the risk of prognosis.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38922373
Delivery date: 19 Mar 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #2: Roof: Roof rail - right side - Dent / paintcoat damage - Smooth repair work



Damage #2: Roof: Roof rail - right side - Dent / paintcoat damage - Smooth repair work



Damage #2: Roof: Roof rail - right side - Dent / paintcoat damage - Smooth repair work



Damage #3: Side panel - rear left side: Side panel - Scratch(...) - Smart repair



Damage #3: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage #4: Roof: Roof - dent(s) - Smooth repair work



Damage #4: Roof: Roof - dent(s) - Smooth repair work



Damage #4: Roof: Roof - dent(s) - Smooth repair work



Damage #4: Roof: Roof - dent(s) - Smooth repair work



Damage #4: Roof: Roof - dent(s) - Smooth repair work



Damage #5: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #5: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #5: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value




Damage #5: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #5: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value




Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #7: Door - rear left side: Door - Scratched - Paint



Damage #7: Door - rear left side: Door - Scratched - Paint



Damage #7: Door - rear left side: Door - Scratched - Paint




Damage #8: Bonnet: Bonnet - Scratched - Paint




Damage #8: Bonnet: Bonnet - Scratched - Paint



Damage #8: Bonnet: Bonnet - Scratched - Paint



Damage #8: Bonnet: Bonnet - Scratched - Paint



Damage #8: Bonnet: Bonnet - Scratched - Paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38922373
Delivery date: 19 Mar 2025



Auto Plus



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint