



**WAUZZZGY2MA075163**

## Vehicle details

<b>Operator</b>		<b>Inspection condition</b>	conditional: light/moisture/ dirt
<b>License number</b>		<b>Mileage (Read)</b>	78,261 km
<b>Manufacturer</b>	Audi	<b>Next maintenance in</b>	2 Monat(e)
<b>Type / Model</b>	A3 40 TFSI e S tronic S line Sportback Sportback5- türig 1395 ccm 204 PS / 150 KW Elektrisch 6-Gang Automatik	<b>Main inspection</b>	
<b>Vehicle Identification number</b>	WAUZZZGY2MA075163	<b>Power / Engine displacement</b>	110 kW / 1,395 ccm
<b>First registration</b>	22 Feb 2021	<b>Upholstery/Colour</b>	Cloth / leather combination / Anthracite- Black
<b>Last maintenance</b>		<b>Paintwork</b>	White
<b>Fuel type</b>	Hybrid Petrol / E	<b>Gearbox</b>	Automatic

## Zustandsbericht

### Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Sill - right side	Trim - Scratch(es) - Smart repair
3	Wing mirror - right side	Mirror housing - Scratch(es) - Smart repair
4	Sill - left side	Trim - Scratch(es) - Smart repair
5	Rear bumper	Rear bumper - Scratch(es) - Smart repair
6	Side panel - rear right side	Wheel arch - Scratch(es) - Smart repair
7	Wheel / tyres	Alloy rim - rear left side (Materialabtrag optisch zu hoch) - Scratched - Loss in value
8	Trim / covers	Boot lining - Scratched - Loss in value
9	Wheel / tyres	Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value
10	Front bumper	Front bumper - Scratched - Repair and paint
11	Roof	Roof - dent(s) - Repair and paint
12	Wheel / tyres	Alloy rim - front right side (Materialabtrag optisch zu hoch) - Scratched - Replace
13	Wheel / tyres	Alloy rim - front left side (Materialabtrag optisch zu hoch) - Scratched - Replace

### Wear and tear

No.	Component group	Description
1	Body	Body (Kratzer,Dellen) - Stone chips - No deduction
2	Seat - front	Seat cover - left side - Worn - No deduction

## Missing parts

### Missing part

## Previous damages

No.	Previous damage
1	Underbody, Provided by user / customer, from 7 May 2022

## Detected repainting

No.	Location
None detectable	

## Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R18 92Y	Pirelli	Summer tyres	4mm - 4mm	Not o.k.	o.k.
2	225/40 R18 92Y	Pirelli	Summer tyres	5mm - 5mm	Not o.k.	o.k.

## Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91T	Goodyear	Winter tyres	5mm - 5mm	Not o.k.	Not o.k.
2	205/55 R16 91T	Goodyear	Winter tyres	6mm - 6mm	Not o.k.	Not o.k.

## Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					12/2024

The wear and tear condition and possible damages to the tyres are considered in the value.

## Equipment

### Equipment

Description
Air conditioning
Navigation unit with map view
Radio

## Comments

Keine Gewähr auf Vollständigkeit und Richtigkeit der angezeigten Ausstattung. Techn. Änderungen vorbehalten.  
Das Fahrzeug weist dem Alter, der Laufleistung und dem Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Autokontor Bayern GmbH  
Windecker Straße 2  
61137 Schöneck

Inspection date: 18 Mar 2025  
**Protocol number: 38906723**



## Vehicle details

<b>Manufacturer</b>	Audi	<b>Inspection condition</b>	conditional: light/ moisture/dirt
<b>Type / Model</b>	A3 40 TFSI e S tronic S line Sportback Sportback5-türig 1395 ccm 204 PS / 150 KW Elektrisch 6-Gang Automatik	<b>Mileage (Read)</b>	78,261 km
<b>Vehicle Identification number</b>	WAUZZZGY2MA075163	<b>First registration</b>	22 Feb 2021

**Vehicle identification:**

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

**Inspection conditions:**

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

**General condition:**

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: VIN



Figure 15: Accessories



Figure 16: Accessories




Figure 17: Documents



Figure 18: Mounted tyres



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.

## Pictures of damage



**Damage #2:** Sill - right side: Trim - Scratch(es) - Smart repair



**Damage #2:** Sill - right side: Trim - Scratch(es) - Smart repair



**Damage #3:** Wing mirror - right side: Mirror housing - Scratch(es) - Smart repair



**Damage #4:** Sill - left side: Trim - Scratch(es) - Smart repair



**Damage #4:** Sill - left side: Trim - Scratch(es) - Smart repair



**Damage #5:** Rear bumper: Rear bumper - Scratch(es) - Smart repair





**Damage #5:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage #6:** Side panel - rear right side: Wheel arch - Scratch(es) - Smart repair



**Damage #6:** Side panel - rear right side: Wheel arch - Scratch(es) - Smart repair



**Damage #6:** Side panel - rear right side: Wheel arch - Scratch(es) - Smart repair



**Damage #7:** Wheel / tyres: Alloy rim - rear left side (Materialabtrag optisch zu hoch) - Scratched - Loss in value



**Damage #7:** Wheel / tyres: Alloy rim - rear left side (Materialabtrag optisch zu hoch) - Scratched - Loss in value



**Damage #8:** Trim / covers: Boot lining - Scratched - Loss in value



**Damage #8:** Trim / covers: Boot lining - Scratched - Loss in value



**Damage #8:** Trim / covers: Boot lining - Scratched - Loss in value



**Damage #9:** Wheel / tyres: Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value



**Damage #9:** Wheel / tyres: Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value



**Damage #9:** Wheel / tyres: Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value



**Damage #10:** Front bumper: Front bumper - Scratched - Repair and paint




**Damage #10:** Front bumper: Front bumper - Scratched - Rep... and paint



**Damage #10:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #11:** Roof: Roof - dent(s) - Repair and paint



**Damage #11:** Roof: Roof - dent(s) - Repair and paint



**Damage #12:** Wheel / tyres: Alloy rim - front right side (Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #12:** Wheel / tyres: Alloy rim - front right side  
(Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #12:** Wheel / tyres: Alloy rim - front right side  
(Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #12:** Wheel / tyres: Alloy rim - front right side  
(Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #13:** Wheel / tyres: Alloy rim - front left side  
(Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #13:** Wheel / tyres: Alloy rim - front left side  
(Materialabtrag optisch zu hoch) - Scratched - Replace



**Damage #13:** Wheel / tyres: Alloy rim - front left side  
(Materialabtrag optisch zu hoch) - Scratched - Replace