



WBY61EF0805W96152

Vehicle details

Operator		Inspection condition	conditional: light/moisture/ dirt
License number		Mileage (Read)	37,191 km
Manufacturer	BMW	Next maintenance in	1 Monat(e)
Type / Model	iX1 xDrive30 Sports Utility Vehicle5-türig 0 ccm 313 PS / 230 KW Elektrisch Automatik	Main inspection	
Vehicle Identification number	WBY61EF0805W96152	Power / Engine displacement	/ 0 ccm
First registration	7 Jul 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Wheel / tyres	Tyre - front left side - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Body	Body - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/65 R17 100H	Pirelli	Winter tyres	6mm - 6mm	o.k.	o.k.
2	205/65 R17 100H	Pirelli	Winter tyres	7mm - 7mm	o.k.	o.k.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 14 Apr 2025
Protocol number: 39308340



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102Y	Continental	Summer tyres	5mm - 5mm	o.k.	o.k.
2	225/55 R18 102Y	Continental	Summer tyres	4mm - 4mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Air conditioning
Navigation unit with map view
Radio

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 14 Apr 2025
Protocol number: 39308340



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	iX1 xDrive30 Sports Utility Vehicle5-türig 0 ccm 313 PS / 230 KW Elektrisch Automatik	Mileage (Read)	37,191 km
Vehicle Identification number	WBY61EF0805W96152	First registration	7 Jul 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Misc.




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.

Pictures of damage



Damage #1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage #1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage #2: Wheel / tyres: Tyre - front left side - Broken / torn - Replace



Damage #2: Wheel / tyres: Tyre - front left side - Broken / torn - Replace



Damage #2: Wheel / tyres: Tyre - front left side - Broken / torn - Replace



Damage #2: Wheel / tyres: Tyre - front left side - Broken / torn - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 14 Apr 2025
Protocol number: 39308340



Auto Plus



Damage #2: Wheel / tyres: Tyre - front left side - Broken / torn - Replace