



WAUZZZF44KA091330

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	140,846 km
Manufacturer	Audi	Next maintenance in	10,200 km
Type / Model	A4 Avant	Main inspection (Report on hand)	06/2026
Vehicle Identification number	WAUZZZF44KA091330	Power / Engine displacement	140 kW / 1,968 ccm
First registration	5 Jun 2019	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Wartungsnachweise fehlen) - No deduction
2	Boot lid / rear door	Boot lid - Scratch(es) - Cover / polish
3	Door - rear left side	Door - Glued / labelled - De-glue / neutralise
4	Door - rear right side	Door - Glued / labelled - De-glue / neutralise
5	Equipment	Tirefit filler - Expired - Replace
6	Wing mirror - left side	Mirror housing - Scratched - Loss in value
7	Body	Door seal - front left side - Damaged - Replace
8	Rear bumper	Spoiler - Scratched - Replace
9	2nd wheel set	Alloy rim set - complete - Scratched - Loss in value
10	Vehicle glazing	Windscreen with rain sensor - Stone chips - Replace
11	Rear bumper	Rear bumper - Scratched - Repair and paint
12	Front bumper	Front bumper - Scratched - Repair and paint
13	Door - front right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 10 Apr 2025

Protocol number: 39347250

Delivery date: 10 Apr 2025



Auto Plus

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94H	Dunlop	Winter tyres	5mm - 5mm	o.k.	
2	225/50 R17 98H	Goodyear	Winter tyres	8mm - 8mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/35 R19 93Y	Pirelli	Summer tyres	3mm - 3mm	o.k.	
2	245/35 R19 93Y	Pirelli	Summer tyres	3mm - 3mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					04/2023

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 10 Apr 2025

Protocol number: 39347250

Delivery date: 10 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	A4 Avant	Mileage (Read)	140,846 km
Vehicle Identification number	WAUZZZF44KA091330	First registration	5 Jun 2019

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #2: Boot lid / rear door: Boot lid - Scratch(es) - Cover / polish



Damage #2: Boot lid / rear door: Boot lid - Scratch(es) - Cove...
polish



Damage #2: Boot lid / rear door: Boot lid - Scratch(es) - Cover /
polish



Damage #3: Door - rear left side: Door - Glued / labelled - De-
glue / neutralise



Damage #3: Door - rear left side: Door - Glued / labelled - De-glu...
neutralise



Damage #4: Door - rear right side: Door - Glued / labelled - De-
glue / neutralise



Damage #4: Door - rear right side: Door - Glued / labelled - De-glue / neutralise



Damage #7: Body: Door seal - front left side - Damaged - Replace



Damage #8: Rear bumper: Spoiler - Scratched - Replace



Damage #6: Wing mirror - left side: Mirror housing - Scratches...
Loss in value



Damage #7: Body: Door seal - front left side - Damaged - Replace



Damage #8: Rear bumper: Spoiler - Scratched - Replace




Damage #8: Rear bumper: Spoiler - Scratched - Replace



Damage #9: 2nd wheel set: Alloy rim set - complete - Scratch...
- Loss in value



Damage #9: 2nd wheel set: Alloy rim set - complete - Scratched -
Loss in value



Damage #9: 2nd wheel set: Alloy rim set - complete - Scratch...
- Loss in value



Damage #9: 2nd wheel set: Alloy rim set - complete - Scratched -
Loss in value




Damage #9: 2nd wheel set: Alloy rim set - complete - Scratch...
- Loss in value



Damage #10: Vehicle glazing: Windscreen with rain sensor - Stone chips - Replace




Damage #10: Vehicle glazing: Windscreen with rain sensor - Stone chips - Replace



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #12: Front bumper: Front bumper - Scratched - Rep... and paint



Damage #12: Front bumper: Front bumper - Scratched - Repair and paint



Damage #12: Front bumper: Front bumper - Scratched - Rep... and paint



Damage #13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage #13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39347250
Delivery date: 10 Apr 2025



Auto Plus



Damage #13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint