



WBA5P51040FL16704

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	41,741 km
Manufacturer	BMW	Next maintenance in	15,000 km
Type / Model	330e	Main inspection (Report on hand)	05/2026
Vehicle Identification number	WBA5P51040FL16704	Power / Engine displacement	135 kW / 1,998 ccm
First registration	29 Mar 2021	Upholstery/Colour	/
Last maintenance	05/2024, 35,096 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
3	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
4	Front bumper	Front bumper - Scratched - Smart repair
5	2nd wheel set	1 tyre - Damaged - Replace
6	2nd wheel set	2 tyres - Worn - Replace
7	2nd wheel set	3 alloy rims - Scratched - Loss in value
8	Sill - right side	Trim - Scratched - Paint
9	Rear bumper	Rear bumper - Scratched - Repair and paint
10	Vehicle glazing	Windscreen - Stone chips - Replace
11	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
12	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front left side	Door edge - Scratched - No deduction
2	Body	Body - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 2 Apr 2025

Protocol number: 39135823

Delivery date: 2 Apr 2025



Auto Plus

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R19 93Y	Bridgestone	Summer tyres	5mm - 5mm	Not o.k.	
2	255/35 R19 96Y	Bridgestone	Summer tyres	2mm - 2mm	Not o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 2 Apr 2025

Protocol number: 39135823

Delivery date: 2 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e	Mileage (Read)	41,741 km
Vehicle Identification number	WBA5P51040FL16704	First registration	29 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.


Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction




Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Front bumper: Front bumper - Scratched - Smart repair



Damage #4: Front bumper: Front bumper - Scratched - Smart repair



Damage #5: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #5: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #6: 2nd wheel set: 2 tyres - Worn - Replace



Damage #6: 2nd wheel set: 2 tyres - Worn - Replace



Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value




Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #7: 2nd wheel set: 3 alloy rims - Scratched - Loss in value



Damage #8: Sill - right side: Trim - Scratched - Paint



Damage #8: Sill - right side: Trim - Scratched - Paint




Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #10: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #10: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #11: Door - rear left side: Door - Dent / paintcoat damage...
Repair and paint



Damage #11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 2 Apr 2025
Protocol number: 39135823
Delivery date: 2 Apr 2025



Auto Plus



Damage #12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #12: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint