

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39204349
Delivery date: 7 Apr 2025



Auto Plus



WBA6N71040FK99912

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	66,951 km
Manufacturer	BMW	Next maintenance in	22,000 km
Type / Model	330e xDrive	Main inspection (Report not on hand)	03/2026
Vehicle Identification number	WBA6N71040FK99912	Power / Engine displacement	135 kW / 1,998 ccm
First registration	3 Mar 2021	Upholstery/Colour	/
Last maintenance	11/2024, 56,140 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic



Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
3	Wheel / tyres	Tyre - rear right side - Damaged - No deduction
4	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
5	Wheel / tyres	Tyre - front right side - Damaged - No deduction
6	Roof	Roof rail - right side - Scratch(es) - Cover / polish
7	Documents	Main inspection certificate (Fehlt) - Replace
8	Documents	Log book (Fehlt) - Replace
9	Trim / covers	Boot lid - interior trim - Scratched - Loss in value
10	Front bumper	Cover bumper - front (Vr) - Scratched - Replace
11	Fuel system	Tank cap - Scratched - Paint
12	Wing mirror - right side	Mirror housing - Scratched - Smart repair
13	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
14	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
15	Front axle	Axles / undercarriage - Malposition - Set / adjust
16	2nd wheel set	2 alloy rims - Scratched - Loss in value
17	2nd wheel set	2 tyres - Worn - Replace
18	Mudguard - left side	Mudguard - left side - Scratched - Paint
19	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
20	Rear bumper	Rear bumper - Scratched - Repair and paint
21	Door - rear left side	Door - Scratched - Paint
22	Door - rear right side	Door - Scratched - Paint
23	Front bumper	Front bumper - Scratched - Repair and paint
24	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
25	Side panel - rear right side	Side panel - Scratch(es) - Paint
26	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part



Previous damages

No.	Previous damage
1	Front, Rear, Provided by user / customer

Detected repainting

No.	Location
1	Boot lid / rear door, Bumper rear, Bumper front, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	5mm - 5mm	Not o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	5mm - 5mm	Not o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Bridgestone	Summer tyres	4mm - 4mm	Not o.k.	
2	255/40 R18 99Y	Bridgestone	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n .i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025

Protocol number: 39204349

Delivery date: 7 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e xDrive	Mileage (Read)	66,951 km
Vehicle Identification number	WBA6N71040FK99912	First registration	3 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - ...
deduction




Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched
- No deduction




Damage #2: Wheel / tyres: Alloy rim - rear right side - Scratched -
No deduction



Damage #2: Wheel / tyres: Alloy rim - rear right side -
Scratched - No deduction



Damage #3: Wheel / tyres: Tyre - rear right side - Damaged - No
deduction



Damage #3: Wheel / tyres: Tyre - rear right side - Damaged -
No deduction




Damage #3: Wheel / tyres: Tyre - rear right side - Damaged - No deduction




Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #5: Wheel / tyres: Tyre - front right side - Damaged - No deduction



Damage #5: Wheel / tyres: Tyre - front right side - Damaged - No deduction



Damage #6: Roof: Roof rail - right side - Scratch(es) - Cover / polish




Damage #6: Roof: Roof rail - right side - Scratch(es) - Cover / polish



Damage #9: Trim / covers: Boot lid - interior trim - Scratched - Loss in value



Damage #9: Trim / covers: Boot lid - interior trim - Scratched - Loss in value



Damage #9: Trim / covers: Boot lid - interior trim - Scratched - Loss in value



Damage #10: Front bumper: Cover bumper - front (Vr) - Scratched - Replace



Damage #10: Front bumper: Cover bumper - front (Vr) - Scratched...
Replace




Damage #10: Front bumper: Cover bumper - front (Vr) -
Scratched - Replace



Damage #11: Fuel system: Tank cap - Scratched - Paint



Damage #11: Fuel system: Tank cap - Scratched - Paint



Damage #11: Fuel system: Tank cap - Scratched - Paint



Damage #12: Wing mirror - right side: Mirror housing -
Scratched - Smart repair



Damage #12: Wing mirror - right side: Mirror housing - Scratched - Smart repair




Damage #13: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage #14: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage #13: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage #14: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage #14: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage #15: Front axle: Axles / undercarriage - Malposition - Set / adjust



Damage #16: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #16: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #16: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #16: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #17: 2nd wheel set: 2 tyres - Worn - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39204349
Delivery date: 7 Apr 2025



Damage #17: 2nd wheel set: 2 tyres - Worn - Replace



Damage #17: 2nd wheel set: 2 tyres - Worn - Replace




Damage #18: Mudguard - left side: Mudguard - left side - Scratch...
- Paint



Damage #18: Mudguard - left side: Mudguard - left side -
Scratched - Paint




Damage #18: Mudguard - left side: Mudguard - left side - Scratch...
- Paint



Damage #18: Mudguard - left side: Mudguard - left side -
Scratched - Paint




Damage #19: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage #19: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage #20: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #20: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #20: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #20: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #20: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #21: Door - rear left side: Door - Scratched - Paint




Damage #21: Door - rear left side: Door - Scratched - Paint




Damage #21: Door - rear left side: Door - Scratched - Paint




Damage #22: Door - rear right side: Door - Scratched - Paint



Damage #22: Door - rear right side: Door - Scratched - Paint




Damage #22: Door - rear right side: Door - Scratched - Paint




Damage #23: Front bumper: Front bumper - Scratched - Repair and paint




Damage #23: Front bumper: Front bumper - Scratched - Rep... and paint



Damage #23: Front bumper: Front bumper - Scratched - Rep... and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #24: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #25: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage #26: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage #25: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage #26: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage #26: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint


TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39204349
Delivery date: 7 Apr 2025



Auto Plus



Damage #26: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint