



WBA5X91010FL21740

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	38,441 km
Manufacturer	BMW	Next maintenance in	18,000 km
Type / Model	330d	Main inspection (Report on hand)	04/2026
Vehicle Identification number	WBA5X91010FL21740	Power / Engine displacement	210 kW / 2,993 ccm
First registration	12 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
2	Bonnet	Bonnet - dent(s) - Smooth repair work
3	Roof	Roof - dent(s) - Smooth repair work
4	Front bumper	Front bumper - Scratched - Smart repair
5	Mudguard - left side	Mudguard - left side - Scratched - Repair and paint
6	Door - front left side	Door - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Rear, Provided by user / customer

Detected repainting

No.	Location
1	Side panel - rear left side, Side panel - rear right side, Door - rear right side, Door - front right side

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39500825

Delivery date: 29 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R19 93Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	
2	255/35 R19 96Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39500825

Delivery date: 29 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330d	Mileage (Read)	38,441 km
Vehicle Identification number	WBA5X91010FL21740	First registration	12 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39500825
Delivery date: 29 Apr 2025



Auto Plus



Figure 19: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #2: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage #2: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage #3: Roof: Roof - dent(s) - Smooth repair work




Damage #3: Roof: Roof - dent(s) - Smooth repair work



Damage #4: Front bumper: Front bumper - Scratched - Smart repair




Damage #4: Front bumper: Front bumper - Scratched - Smart repair




Damage #5: Mudguard - left side: Mudguard - left side - Scratched - Repair and paint



Damage #5: Mudguard - left side: Mudguard - left side - Scratched - Repair and paint



Damage #5: Mudguard - left side: Mudguard - left side - Scratched - Repair and paint



Damage #6: Door - front left side: Door - Scratched - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39500825

Delivery date: 29 Apr 2025



Auto Plus



Damage #6: Door - front left side: Door - Scratched - Repair and paint