



WBA41FY010FS28900

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	22,043 km
Manufacturer	BMW	Next maintenance in	11,000 km
Type / Model	320e	Main inspection (Read from ZBI)	12/2026
Vehicle Identification number	WBA41FY010FS28900	Power / Engine displacement	120 kW / 1,998 ccm
First registration	8 Dec 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Rear bumper	Rear bumper - Scratched - Repair and paint
4	Door - rear right side	Door - Scratched - Repair and paint
5	Roof	Roof - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98V	Pirelli	Winter tyres	8mm - 8mm	o.k.	
2	225/50 R17 98V	Pirelli	Winter tyres	7mm - 7mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39539791
Delivery date: 2 May 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Hankook	Summer tyres	7mm - 7mm	o.k.	
2	225/50 R17 98Y	Hankook	Summer tyres	7mm - 7mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39539791
Delivery date: 2 May 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	320e	Mileage (Read)	22,043 km
Vehicle Identification number	WBA41FY010FS28900	First registration	8 Dec 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39539791
Delivery date: 2 May 2025



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39539791
Delivery date: 2 May 2025



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.


Pictures of damage




Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #3: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #3: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Roof: Roof - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39539791
Delivery date: 2 May 2025



Auto Plus



Damage #5: Roof: Roof - Scratched - Repair and paint