



**WBAJP310X0CD50993**

## Vehicle details

|                               |                                          |                             |                                  |
|-------------------------------|------------------------------------------|-----------------------------|----------------------------------|
| Operator                      |                                          | Inspection condition        | conditional: light/moisture/dirt |
| License number                |                                          | Mileage (Read)              | 54,696 km                        |
| Manufacturer                  | BMW                                      | Next maintenance in         | 7,000 km                         |
| Type / Model                  | 5er-Reihe 520d Touring A<br>Kombi5-türig | Main inspection             |                                  |
| Vehicle Identification number | WBAJP310X0CD50993                        | Power / Engine displacement | / 1,995 ccm                      |
| First registration            | 9 Dec 2018                               | Upholstery/Colour           | Cloth / Black                    |
| Last maintenance              |                                          | Paintwork                   | White                            |
| Fuel type                     | Diesel                                   | Gearbox                     | Automatic                        |

## Zustandsbericht

### Value reducing factors

| No. | Component group              | Description                                                            |
|-----|------------------------------|------------------------------------------------------------------------|
| 1   | Trim / covers                | Brightware / decorative strip (Vr Einstiegsleiste) - dent(s) - Replace |
| 2   | Braking system               | Brake fluid - Due - Replace                                            |
| 3   | Side panel - rear right side | Sill - dent(s) - Smooth repair work                                    |
| 4   | Sill - left side             | Sill - Scratch(es) - Smart repair                                      |
| 5   | Instrument panel             | Indicator light (Folgekosten möglich) - on - Perform diagnosis         |
| 6   | Trim / covers                | Roof lining - Scratch(es) - Loss in value                              |
| 7   | Front bumper                 | Front bumper - Scratched - Repair and paint                            |
| 8   | Rear bumper                  | Rear bumper - Dent / paintcoat damage - Repair and paint               |
| 9   | Boot lid / rear door         | Boot lid - Scratch(es) - Repair and paint                              |

### Wear and tear

| No. | Component group | Description                       |
|-----|-----------------|-----------------------------------|
| 1   | Body            | Body - Stone chips - No deduction |

### Missing parts

|              |
|--------------|
| Missing part |
|--------------|

### Detected repainting

| No.             | Location |
|-----------------|----------|
| None detectable |          |



## Main tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/55 R17 97H | Pirelli      | Winter tyres | 5mm - 5mm   | o.k.       | o.k.           |
| 2    | 225/55 R17 97H | Pirelli      | Winter tyres | 5mm - 5mm   | o.k.       | o.k.           |

## Additional tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/55 R17 97Y | Pirelli      | Summer tyres | 5mm - 5mm   | o.k.       | o.k.           |
| 2    | 225/55 R17 97Y | Continental  | Summer tyres | 5mm - 5mm   | o.k.       | o.k.           |

The wear and tear condition and possible damages to the tyres are considered in the value.

## Equipment

### Equipment

| Description                   |
|-------------------------------|
| Air conditioning              |
| Navigation unit with map view |
| Radio                         |

## Comments

Keine Gewähr auf Vollständigkeit und  
Richtigkeit der angezeigten Ausstattung.  
Techn. Änderungen vorbehalten.  
Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Autokontor Bayern GmbH  
Windecker Straße 2  
61137 Schöneck

Inspection date: 14 Apr 2025  
**Protocol number: 39373981**



Auto Plus

## Vehicle details

|                                      |                                       |                             |                                  |
|--------------------------------------|---------------------------------------|-----------------------------|----------------------------------|
| <b>Manufacturer</b>                  | BMW                                   | <b>Inspection condition</b> | conditional: light/moisture/dirt |
| <b>Type / Model</b>                  | 5er-Reihe 520d Touring A Kombi5-türig | <b>Mileage (Read)</b>       | 54,696 km                        |
| <b>Vehicle Identification number</b> | WBAJP310X0CD50993                     | <b>First registration</b>   | 9 Dec 2018                       |

### Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

### Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

### General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



**Figure 1:** Diagonal front



**Figure 2:** Diagonal front



**Figure 3:** Diagonal rear



**Figure 4:** Diagonal rear



**Figure 5:** Interior



**Figure 6:** Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: Interior




Figure 15: VIN



Figure 16: Documents



Figure 17: Documents



Figure 18: Documents



Figure 19: Documents



Figure 20: Documents




Figure 21: Documents




Figure 22: Documents



Figure 23: Mounted tyres



Figure 24: Mounted tyres



Figure 25: Mounted tyres



Figure 26: Mounted tyres



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Autokontor Bayern GmbH  
Windecker Straße 2  
61137 Schöneck

Inspection date: 14 Apr 2025  
**Protocol number: 39373981**



**Figure 37: Misc.**



**Figure 38: Misc.**


## Pictures of damage




**Damage #1:** Trim / covers: Brightware / decorative strip (Vr Einstiegsleiste) - dent(s) - Replace



**Damage #1:** Trim / covers: Brightware / decorative strip (Vr Einstiegsleiste) - dent(s) - Replace




**Damage #2:** Braking system: Brake fluid - Due - Replace



**Damage #3:** Side panel - rear right side: Sill - dent(s) - Smooth repair work



**Damage #3:** Side panel - rear right side: Sill - dent(s) - Smooth repair work



**Damage #4:** Sill - left side: Sill - Scratch(es) - Smart repair work



**Damage #4:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage #5:** Instrument panel: Indicator light (Folgekosten möglich) - on - Perform diagnosis



**Damage #6:** Trim / covers: Roof lining - Scratch(es) - Loss in value



**Damage #6:** Trim / covers: Roof lining - Scratch(es) - Loss in value



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint




**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #8:** Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



**Damage #8:** Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



**Damage #8:** Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



**Damage #8:** Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Autokontor Bayern GmbH  
Windecker Straße 2  
61137 Schöneck

Inspection date: 14 Apr 2025  
**Protocol number: 39373981**



Auto Plus



**Damage #9:** Boot lid / rear door: Boot lid - Scratch(es) - Repair and paint



**Damage #9:** Boot lid / rear door: Boot lid - Scratch(es) - Repair and paint



**Damage #9:** Boot lid / rear door: Boot lid - Scratch(es) - Repair and paint