



WBA21FY090FS20924

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	58,631 km
Manufacturer	BMW	Next maintenance in	7,000 km
Type / Model	320i	Main inspection (Read from ZBI)	01/2027
Vehicle Identification number	WBA21FY090FS20924	Power / Engine displacement	135 kW / 1,998 ccm
First registration	4 Jan 2024	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Scratched - Smart repair
2	Rear bumper	Rear bumper - Scratched - Repair and paint
3	Front bumper	Front bumper - Scratched - Repair and paint
4	Side panel - rear left side	Side panel - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Side - left, Provided by user / customer

Detected repainting

No.	Location
	None detectable

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 96H	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	205/60 R16 96H	Goodyear	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39496373
Delivery date: 28 Apr 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Hankook	Summer tyres	5mm - 5mm	o.k.	
2	225/50 R17 98Y	Hankook	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025

Protocol number: 39496373

Delivery date: 28 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	320i	Mileage (Read)	58,631 km
Vehicle Identification number	WBA21FY090FS20924	First registration	4 Jan 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior




Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39496373
Delivery date: 28 Apr 2025



Figure 19: Misc.



Figure 20: Misc.


Pictures of damage



Damage #1: Wing mirror - right side: Mirror housing - Scratched - Smart repair



Damage #1: Wing mirror - right side: Mirror housing - Scratch... - Smart repair




Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #3: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Front bumper: Front bumper - Scratched - Repair and paint




Damage #4: Side panel - rear left side: Side panel - Scratched - Repair and paint



Damage #4: Side panel - rear left side: Side panel - Scratched - Repair and paint



Damage #4: Side panel - rear left side: Side panel - Scratched - Repair and paint



Damage #4: Side panel - rear left side: Side panel - Scratched - Repair and paint