



WBA5P51000FN09142

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	69,072 km
Manufacturer	BMW	Next maintenance in	27,000 km
Type / Model	330e	Main inspection (Read from ZBI)	06/2025
Vehicle Identification number	WBA5P51000FN09142	Power / Engine displacement	135 kW / 1,998 ccm
First registration	13 Jun 2022	Upholstery/Colour	/
Last maintenance	02/2025, 62,229 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratched - No deduction
2	Braking system	Brake fluid - Due - Replace
3	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
4	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
5	Side panel - rear right side	Sill - Scratch(es) - Smart repair
6	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
7	Wheel / tyres	Tyre - front right side - Damaged - Replace
8	Door - rear left side	Door - dent(s) - Smooth repair work
9	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
10	Rear bumper	Rear bumper - Scratch(es) - Paint
11	Front bumper	Front bumper - Scratched - Repair and paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Apr 2025
Protocol number: 39444681
Delivery date: 24 Apr 2025



Auto Plus

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Hankook	Summer tyres	6mm - 6mm	Not o.k.	
2	225/50 R17 98Y	Hankook	Summer tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Apr 2025
Protocol number: 39444681
Delivery date: 24 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e	Mileage (Read)	69,072 km
Vehicle Identification number	WBA5P51000FN09142	First registration	13 Jun 2022

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.





Figure 21: Misc.




Figure 22: Misc.

Pictures of damage



Damage #1: Door - front left side: Door edge - Scratched - No deduction




Damage #2: Braking system: Brake fluid - Due - Replace




Damage #3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage #3: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair




Damage #4: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage #4: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage #5: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage #5: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage #6: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage #6: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage #7: Wheel / tyres: Tyre - front right side - Damaged - Replace




Damage #7: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage #8: Door - rear left side: Door - dent(s) - Smooth repair work




Damage #8: Door - rear left side: Door - dent(s) - Smooth repair work




Damage #8: Door - rear left side: Door - dent(s) - Smooth repair work



Damage #9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage #9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage #9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage #10: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage #10: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #10: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #10: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #11: Front bumper: Front bumper - Scratched - Repair a...
paint



Damage #11: Front bumper: Front bumper - Scratched - Rep...
and paint



Damage #11: Front bumper: Front bumper - Scratched - Repair and paint




Damage #11: Front bumper: Front bumper - Scratched - Repair and paint



Damage #11: Front bumper: Front bumper - Scratched - Repair and paint



Damage #12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage #12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage #12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint


TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Apr 2025
Protocol number: 39444681
Delivery date: 24 Apr 2025



Auto Plus



Damage #12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint