



WBA6K51020FL20513

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	74,800 km
Manufacturer	BMW	Next maintenance in	-700 km
Type / Model	330i	Main inspection (Report on hand)	04/2026
Vehicle Identification number	WBA6K51020FL20513	Power / Engine displacement	190 kW / 1,998 ccm
First registration	16 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 tyre - Damaged - No deduction
2	Roof	Roof rail - right side - dent(s) - Smooth repair work
3	Misc.	Inspection / maintenance - Due - Perform
4	Front bumper	Front bumper (Gebrochen) - Damaged - Replace

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Bridgestone	Summer tyres	3mm - 3mm	o.k.	
2	255/40 R18 99Y	Bridgestone	Summer tyres	3mm - 3mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39511423
Delivery date: 29 Apr 2025



The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39511423

Delivery date: 29 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	330i	Mileage (Read)	74,800 km
Vehicle Identification number	WBA6K51020FL20513	First registration	16 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39511423

Delivery date: 29 Apr 2025



Auto Plus



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.




Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.


Pictures of damage




Damage #1: 2nd wheel set: 1 tyre - Damaged - No deduction




Damage #2: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage #2: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage #3: Misc.: Inspection / maintenance - Due - Perform



Damage #4: Front bumper: Front bumper (Gebrochen) - Damaged - Replace



Damage #4: Front bumper: Front bumper (Gebrochen) - Damaged - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39511423
Delivery date: 29 Apr 2025



Auto Plus



Damage #4: Front bumper: Front bumper (Gebrochen) - Damaged
- Replace