



WBA5P51060FK96844

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	142,973 km
Manufacturer	BMW	Next maintenance in	21,000 km
Type / Model	330e	Main inspection (Report on hand)	03/2026
Vehicle Identification number	WBA5P51060FK96844	Power / Engine displacement	135 kW / 1,998 ccm
First registration	5 Mar 2021	Upholstery/Colour	Cloth / leather combination / Black
Last maintenance	11/2024, 130,586 km	Paintwork	Blue
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Smart repair
4	Roof	Roof - Scratch(es) - Smart repair
5	Steering system	Steering wheel - Scratch(es) - Smart repair
6	Bonnet	Bonnet - Scratch(es) - Smart repair
7	Front bumper	Front bumper - Scratch(es) - Smart repair
8	Door - front left side	Door - Scratch(es) - Smart repair
9	Trim / covers	Door trim - rear left side - Scratch(es) - Smart repair
10	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
11	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
12	2nd wheel set	Alloy rim set - complete - Scratch(es) - Loss in value
13	Sill - right side	Sill - Scratch(es) - Paint
14	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Comfort Autotechnik GmbH
Wiesenstraße 52
40549 Düsseldorf

Inspection date: 1 Apr 2025
Protocol number: 39334131



Auto Plus

No.	Location
1	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94H	Dunlop	Winter tyres	6mm - 6mm	o.k.	o.k.
2	225/50 R17 94H	Dunlop	Winter tyres	6mm - 6mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Dunlop	Summer tyres	4mm - 4mm	o.k.	o.k.
2	225/45 R18 95Y	Dunlop	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n.i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Comfort Autotechnik GmbH
Wiesenstraße 52
40549 Düsseldorf

Inspection date: 1 Apr 2025
Protocol number: 39334131



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	330e	Mileage (Read)	142,973 km
Vehicle Identification number	WBA5P51060FK96844	First registration	5 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear




Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior




Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: Interior



Figure 15: Interior



Figure 16: VIN




Figure 17: Documents




Figure 18: Documents

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Comfort Autotechnik GmbH
Wiesenstraße 52
40549 Düsseldorf

Inspection date: 1 Apr 2025
Protocol number: 39334131




Figure 19: Documents



Figure 20: Documents



Figure 21: Documents




Figure 22: Mounted tyres




Figure 23: Mounted tyres



Figure 24: Mounted tyres



Figure 25: Mounted tyres



Figure 26: Mounted tyres



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.


Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Smart repair




Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Smart repair




Damage #2: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Smart repair



Damage #2: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Smart repair



Damage #3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Smart repair



Damage #3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Smart repair




Damage #4: Roof: Roof - Scratch(es) - Smart repair




Damage #4: Roof: Roof - Scratch(es) - Smart repair




Damage #4: Roof: Roof - Scratch(es) - Smart repair



Damage #5: Steering system: Steering wheel - Scratch(es) - Smart repair



Damage #5: Steering system: Steering wheel - Scratch(es) - Smart repair



Damage #6: Bonnet: Bonnet - Scratch(es) - Smart repair




Damage #6: Bonnet: Bonnet - Scratch(es) - Smart repair



Damage #7: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage #7: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage #7: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage #7: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage #8: Door - front left side: Door - Scratch(es) - Smart repair



Damage #8: Door - front left side: Door - Scratch(es) - Smart repair




Damage #8: Door - front left side: Door - Scratch(es) - Smart repair



Damage #9: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair




Damage #9: Trim / covers: Door trim - rear left side - Scratch(es) - Smart repair




Damage #10: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage #10: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage #11: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage #11: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value




Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value




Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value




Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #12: 2nd wheel set: Alloy rim set - complete - Scratch(es) - Loss in value



Damage #13: Sill - right side: Sill - Scratch(es) - Paint



Damage #13: Sill - right side: Sill - Scratch(es) - Paint



Damage #14: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage #14: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage #14: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Comfort Autotechnik GmbH
Wiesenstraße 52
40549 Düsseldorf

Inspection date: 1 Apr 2025
Protocol number: 39334131



Auto Plus



Damage #14: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint