


Vehicle details

VIN	WF0JXXGAH JLR64738	Brand	FORD	Maintenance date	-
Licence Plate	H9-14-KS	Model	FIESTA 1.0 EcoBoost 92kW ST-Line X 5d	Maintenance mileage	-
Registration date	28/02/2020	Year	2020	Exterior Color	Black Metallic
Odometer	174 789 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	28/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Rear parcel shelf	✗
Spare wheel kit	✓



Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

2		Part Position Damages Severity Repair mode	Bumper Front Scratched - Repair	3		Part Position Damages Severity Repair mode	Alloy wheel 17" Front left Scratched - Lumpsum repair
4		Part Position Damages Severity Repair mode	Door Front left Dented Diameter (mm) > 20 Smart Repair	5		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Smart Repair
6		Part Position Damages Severity Repair mode	Alloy wheel 17" Back left Scratched - Lumpsum repair	7		Part Position Damages Severity Repair mode	Bumper Back Dent & Chips - Repair
8		Part Position Damages Severity Repair mode	Alloy wheel 17" Back right Scratched - Lumpsum repair	9		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair
10		Part Position Damages Severity Repair mode	Alloy wheel 17" Front right Scratched - Lumpsum repair	11		Part Position Damages Severity Repair mode	Bonnet - Scratched - Repair
12		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Lumpsum repair	13		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info
14		Part Position Damages Severity Repair mode	Spoiler Back Missing - Replace	15		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips - Repair
18		Part Position Damages Severity Repair mode	Fixed door stop Back right Misaligned - Repair				

Interior damage

1



●

Part	Rear parcel shelf
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

16



● ●

Part	Fabric door lining
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

17



● ●

Part	Interior cleaning
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning