



WBA5F31020FL17390

## Vehicle details

|                               |                   |                                 |                    |
|-------------------------------|-------------------|---------------------------------|--------------------|
| Operator                      |                   | Inspection condition            | Sufficient         |
| License number                |                   | Mileage (Read)                  | 168,079 km         |
| Manufacturer                  | BMW               | Next maintenance in             | 4,100 km           |
| Type / Model                  | 320i              | Main inspection (Read from ZBI) | 04/2026            |
| Vehicle Identification number | WBA5F31020FL17390 | Power / Engine displacement     | 135 kW / 1,998 ccm |
| First registration            | 6 Apr 2021        | Upholstery/Colour               | /                  |
| Last maintenance              |                   | Paintwork                       |                    |
| Fuel type                     | Petrol            | Gearbox                         | Automatic          |

## Zustandsbericht

### Value reducing factors

| No. | Component group             | Description                                                        |
|-----|-----------------------------|--------------------------------------------------------------------|
| 1   | Wheel / tyres               | Alloy rim - rear left side - Scratched - No deduction              |
| 2   | Steering system             | Multi-function steering wheel - leather - Abrasion - Loss in value |
| 3   | Sill - right side           | Sill - Dent / paintcoat damage - Smart repair                      |
| 4   | Seat - rear                 | Armrest - centre - Broken / torn - Replace                         |
| 5   | Door - rear right side      | Door - Scratch(es) - Paint                                         |
| 6   | Rear bumper                 | Rear bumper - Scratched - Repair and paint                         |
| 7   | Door - front right side     | Door - Scratched - Paint                                           |
| 8   | Side panel - rear left side | Side panel - Dent / paintcoat damage - Repair and paint            |

### Wear and tear

| No. | Component group              | Description                             |
|-----|------------------------------|-----------------------------------------|
| 1   | Vehicle glazing              | Windscreen - Stone chips - No deduction |
| 2   | Interior                     | Interior - Abrasion - No deduction      |
| 3   | Body                         | Body - Scratch(es) - No deduction       |
| 4   | Side panel - rear right side | Sill - Scratch(es) - No deduction       |
| 5   | Side panel - rear left side  | Sill - Scratch(es) - No deduction       |
| 6   | Bonnet                       | Bonnet - Stone chips - No deduction     |
| 7   | Door - front left side       | Door edge - Scratched - No deduction    |

### Missing parts

Missing part

### Detected repainting

| No. | Location                                                                                               |
|-----|--------------------------------------------------------------------------------------------------------|
| 1   | Roof rail - right side, Boot lid / rear door, Side panel - rear right side, Professionally carried out |

**TÜV SÜD Auto Partner GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 9 May 2025

**Protocol number:** 39651431

Delivery date: 9 May 2025



## Main tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/50 R17 98H | Pirelli      | Winter tyres | 7mm - 5mm   | o.k.       |                |
| 2    | 225/50 R17 98H | Pirelli      | Winter tyres | 7mm - 7mm   | o.k.       |                |

## Additional tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/50 R17 98Y | Pirelli      | Summer tyres | 6mm - 6mm   | o.k.       |                |
| 2    | 225/50 R17 98Y | Pirelli      | Summer tyres | 6mm - 6mm   | o.k.       |                |

## Replacement

| Type    | Tyre size | Manufacturer | Type of tyre | Tread depth | Expiration date |
|---------|-----------|--------------|--------------|-------------|-----------------|
| Tirefit |           |              |              |             | 07/2026         |

The wear and tear condition and possible damages to the tyres are considered in the value.

## Comments

Keine Gewähr auf Vollständigkeit und  
Richtigkeit der angezeigten Ausstattung.  
Techn. Änderungen vorbehalten  
Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.  
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

**TÜV SÜD Auto Partner GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 9 May 2025

**Protocol number:** 39651431

Delivery date: 9 May 2025



---

## Vehicle details

|                                      |                   |                             |            |
|--------------------------------------|-------------------|-----------------------------|------------|
| <b>Manufacturer</b>                  | BMW               | <b>Inspection condition</b> | Sufficient |
| <b>Type / Model</b>                  | 320i              | <b>Mileage (Read)</b>       | 168,079 km |
| <b>Vehicle Identification number</b> | WBA5F31020FL17390 | <b>First registration</b>   | 6 Apr 2021 |

### Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

### Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

### General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



**Figure 1:** Diagonal front



**Figure 2:** Diagonal front




**Figure 3:** Diagonal rear



**Figure 4:** Diagonal rear



**Figure 5:** Interior



**Figure 6:** Interior





Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.





Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.

## Pictures of damage




**Damage #1:** Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction




**Damage #1:** Wheel / tyres: Alloy rim - rear left side - Scratched - No deduction




**Damage #1:** Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction



**Damage #2:** Steering system: Multi-function steering wheel - leather - Abrasion - Loss in value



**Damage #2:** Steering system: Multi-function steering wheel - leather - Abrasion - Loss in value



**Damage #2:** Steering system: Multi-function steering wheel - leather - Abrasion - Loss in value






**Damage #3:** Sill - right side: Sill - Dent / paintcoat damage - Smart repair




**Damage #3:** Sill - right side: Sill - Dent / paintcoat damage - Smart repair



**Damage #3:** Sill - right side: Sill - Dent / paintcoat damage - Smart repair



**Damage #4:** Seat - rear: Armrest - centre - Broken / torn - Replace



**Damage #4:** Seat - rear: Armrest - centre - Broken / torn - Replace



**Damage #5:** Door - rear right side: Door - Scratch(es) - Paint



**Damage #5:** Door - rear right side: Door - Scratch(es) - Paint



**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint






**Damage #6:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #7:** Door - front right side: Door - Scratched - Paint




**Damage #7:** Door - front right side: Door - Scratched - Paint



**Damage #8:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage #8:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage #8:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



## Pictures of repainting



**Repainting 1:** Roof rail - right side, Boot lid / rear door, Side pane... rear right side



**Repainting 1:** Roof rail - right side, Boot lid / rear door, Side panel - rear right side



**Repainting 1:** Roof rail - right side, Boot lid / rear door, Side pane... rear right side