



WBA6N31060FL23653

## Vehicle details

|                               |                       |                                  |                                  |
|-------------------------------|-----------------------|----------------------------------|----------------------------------|
| Operator                      |                       | Inspection condition             | conditional: light/moisture/dirt |
| License number                |                       | Mileage (Read)                   | 112,910 km                       |
| Manufacturer                  | BMW                   | Next maintenance in              | 11,000 km                        |
| Type / Model                  | 330e                  | Main inspection (Report on hand) | 06/2026                          |
| Vehicle Identification number | WBA6N31060FL23653     | Power / Engine displacement      | 135 kW / 1,998 ccm               |
| First registration            | 10 May 2021           | Upholstery/Colour                | /                                |
| Last maintenance              | 06/2024, 94,439 km    | Paintwork                        |                                  |
| Fuel type                     | Hybr.B/E ext. edition | Gearbox                          | Automatic                        |

## Zustandsbericht

### Value reducing factors

| No. | Component group              | Description                                             |
|-----|------------------------------|---------------------------------------------------------|
| 1   | Wheel / tyres                | Tyre - front - Worn - No deduction                      |
| 2   | Wheel / tyres                | Alloy rim - rear right side - Scratched - No deduction  |
| 3   | Seat - front                 | Seat cover - left side - Abrasion - Loss in value       |
| 4   | Fuel system                  | Tank cap - Scratch(es) - Smart repair                   |
| 5   | Door - rear right side       | Door seal - Damaged - Replace                           |
| 6   | Wing mirror - right side     | Cap - Scratched - Smart repair                          |
| 7   | Sill - left side             | Sill - Scratch(es) - Smart repair                       |
| 8   | Side panel - rear right side | Sill - Scratch(es) - Smart repair                       |
| 9   | Indicator - front            | Mirror - right side - Scratched - Replace               |
| 10  | Mudguard - right side        | Mudguard - right side - Scratch(es) - Smart repair      |
| 11  | Equipment                    | Vehicle key with remote control (Fehlt) - Replace       |
| 12  | 2nd wheel set                | 2 alloy rims - Scratched - Loss in value                |
| 13  | Side panel - rear left side  | Sill - Scratch(es) - Paint                              |
| 14  | Body                         | B-pillar - left side - Scratched - Repair and paint     |
| 15  | Rear bumper                  | Rear bumper - Scratched - Repair and paint              |
| 16  | Front bumper                 | Front bumper - Scratched - Repair and paint             |
| 17  | Side panel - rear left side  | Side panel - Scratch(es) - Paint                        |
| 18  | Side panel - rear right side | Side panel - Dent / paintcoat damage - Repair and paint |
| 19  | Boot lid / rear door         | Boot lid - Dent / paintcoat damage - Repair and paint   |
| 20  | Bonnet                       | Bonnet - Scratch(es) - Paint                            |
| 21  | Door - front right side      | Door - Dent / paintcoat damage - Repair and paint       |



## Wear and tear

| No. | Component group | Description                             |
|-----|-----------------|-----------------------------------------|
| 1   | Body            | Body - Stone chips - No deduction       |
| 2   | Interior        | Interior - Abrasion - No deduction      |
| 3   | Vehicle glazing | Windscreen - Stone chips - No deduction |

## Missing parts

| Missing part |
|--------------|
|--------------|

## Previous damages

| No. | Previous damage                    |
|-----|------------------------------------|
| 1   | Front, Provided by user / customer |

## Detected repainting

| No. | Location                                                                                                      |
|-----|---------------------------------------------------------------------------------------------------------------|
| 1   | Mudguard - left side, Bumper front, Door - rear left side, Door - front left side, Professionally carried out |

## Main tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/50 R17 98V | Pirelli      | Winter tyres | 4mm - 4mm   | Not o.k.   |                |
| 2    | 225/50 R17 98V | Pirelli      | Winter tyres | 5mm - 5mm   | o.k.       |                |

## Additional tyres

| Axle | Tyre size      | Manufacturer | Type of tyre | Tread depth | Roadworthy | Permissibility |
|------|----------------|--------------|--------------|-------------|------------|----------------|
| 1    | 225/45 R18 95Y | Bridgestone  | Summer tyres | 4mm - 4mm   | o.k.       |                |
| 2    | 225/45 R18 95Y | Bridgestone  | Summer tyres | 4mm - 4mm   | o.k.       |                |

The wear and tear condition and possible damages to the tyres are considered in the value.

## Comments

Keine Gewähr auf Vollständigkeit und  
Richtigkeit der angezeigten Ausstattung.  
Techn. Änderungen vorbehalten  
Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.  
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

**TÜV SÜD Auto Partner GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 20 May 2025  
**Protocol number: 39797824**  
Delivery date: 20 May 2025



---

## Vehicle details

|                                      |                   |                             |                                  |
|--------------------------------------|-------------------|-----------------------------|----------------------------------|
| <b>Manufacturer</b>                  | BMW               | <b>Inspection condition</b> | conditional: light/moisture/dirt |
| <b>Type / Model</b>                  | 330e              | <b>Mileage (Read)</b>       | 112,910 km                       |
| <b>Vehicle Identification number</b> | WBA6N31060FL23653 | <b>First registration</b>   | 10 May 2021                      |

### Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

### Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

### General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



**Figure 1:** Diagonal front




**Figure 2:** Diagonal front




**Figure 3:** Diagonal rear



**Figure 4:** Diagonal rear



**Figure 5:** Interior



**Figure 6:** Interior



**Figure 7: Interior**




**Figure 8: Interior**



**Figure 9: Interior**



**Figure 10: Misc.**



**Figure 11: Misc.**



**Figure 12: Misc.**



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.

## Pictures of damage



**Damage #1:** Wheel / tyres: Tyre - front - Worn - No deduction



**Damage #1:** Wheel / tyres: Tyre - front - Worn - No deduction




**Damage #2:** Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction




**Damage #2:** Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



**Damage #2:** Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



**Damage #3:** Seat - front: Seat cover - left side - Abrasion - Low in value




**Damage #3:** Seat - front: Seat cover - left side - Abrasion - Loss in value



**Damage #4:** Fuel system: Tank cap - Scratch(es) - Smart repair



**Damage #4:** Fuel system: Tank cap - Scratch(es) - Smart repair



**Damage #5:** Door - rear right side: Door seal - Damaged - Replace



**Damage #5:** Door - rear right side: Door seal - Damaged - Replace




**Damage #6:** Wing mirror - right side: Cap - Scratched - Smart repair




**Damage #6:** Wing mirror - right side: Cap - Scratched - Smart repair




**Damage #7:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage #7:** Sill - left side: Sill - Scratch(es) - Smart repair



**Damage #8:** Side panel - rear right side: Sill - Scratch(es) - Smart repair



**Damage #8:** Side panel - rear right side: Sill - Scratch(es) - Smart repair



**Damage #9:** Indicator - front: Mirror - right side - Scratched - Replace



**Damage #10:** Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



**Damage #10:** Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



**Damage #12:** 2nd wheel set: 2 alloy rims - Scratched - Loss in value



**Damage #10:** Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



**Damage #12:** 2nd wheel set: 2 alloy rims - Scratched - Loss in value




**Damage #12:** 2nd wheel set: 2 alloy rims - Scratched - Loss in value



**Damage #12:** 2nd wheel set: 2 alloy rims - Scratched - Loss in value




**Damage #13:** Side panel - rear left side: Sill - Scratch(es) - Paint




**Damage #13:** Side panel - rear left side: Sill - Scratch(es) - Paint




**Damage #13:** Side panel - rear left side: Sill - Scratch(es) - Paint



**Damage #14:** Body: B-pillar - left side - Scratched - Repair and paint



**Damage #14:** Body: B-pillar - left side - Scratched - Repair and paint




**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint




**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint




**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #15:** Rear bumper: Rear bumper - Scratched - Repair and paint




**Damage #16:** Front bumper: Front bumper - Scratched - Rep... and paint




**Damage #16:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint




**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint




**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint




**Damage #17:** Side panel - rear left side: Side panel - Scratch(es) - Paint



**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage #19:** Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



**Damage #18:** Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage #19:** Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



**Damage #19:** Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



**Damage #20:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage #20:** Bonnet: Bonnet - Scratch(es) - Paint




**Damage #20:** Bonnet: Bonnet - Scratch(es) - Paint



**Damage #21:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage #21:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage #21:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage #21:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint



**Damage #21:** Door - front right side: Door - Dent / paintcoat damage - Repair and paint