



WBA6N31080FL14775

Vehicle details

Operator		Inspection condition	conditional: light/ moisture/dirt
License number		Mileage (Read)	32,681 km
Manufacturer	BMW	Next maintenance in	-1 Monat(e)
Type / Model	3er-Reihe 330e Touring Advantage Automatic Kombi5-türig 1998 ccm 292 PS / 215 KW Elektrisch 8-Gang Automatik		
Vehicle Identification number	WBA6N31080FL14775	Power / Engine displacement	215 kW / 1,998 ccm
First registration	1 Apr 2021	Upholstery/Colour	Cloth / Anthracite-Grey
Last maintenance		Paintwork	Blue
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door seal - Differs from the original configuration - Replace
2	Wheel / tyres	Alloy rim - front right side (Materialabtrag optisch gering) - Scratched - Loss in value
3	Wheel / tyres	Alloy rim - front left side (Materialabtrag optisch gering) - Scratched - Loss in value
4	Wheel / tyres	Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value
5	Sill - right side	Trim - Scratched - Repair and paint
6	Front bumper	Front bumper - Scratched - Repair and paint
7	Misc.	Inspection / maintenance - Due - Replace

Wear and tear

No.	Component group	Description
1	Body	Body (Kratzer,Dellen) - Stone chips - No deduction
2	2nd wheel set	1 alloy rim - Scratched - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R19 93Y	Bridgestone	Summer tyres	4mm - 4mm	Not o.k.	o.k.
2	255/35 R19 96Y	Bridgestone	Summer tyres	5mm - 5mm	Not o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Goodyear	Winter tyres	7mm - 7mm	Not o.k.	Not o.k.
2	225/50 R17 98H	Goodyear	Winter tyres	7mm - 7mm	Not o.k.	Not o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Air conditioning
Navigation unit with map view
Radio

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 28 May 2025
Protocol number: 40022124



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/ moisture/dirt
Type / Model	3er-Reihe 330e Touring Advantage Automatic Kombi5-türig 1998 ccm 292 PS / 215 KW Elektrisch 8-Gang Automatik	Mileage (Read)	32,681 km
Vehicle Identification number	WBA6N31080FL14775	First registration	1 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: VIN



Figure 15: Accessories



Figure 16: Accessories



Figure 17: Accessories




Figure 18: Documents



Figure 19: Mounted tyres



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.

Pictures of damage



Damage #1: Door - rear right side: Door seal - Differs from the original configuration - Replace



Damage #1: Door - rear right side: Door seal - Differs from the original configuration - Replace




Damage #2: Wheel / tyres: Alloy rim - front right side (Materialabtrag optisch gering) - Scratched - Loss in value



Damage #2: Wheel / tyres: Alloy rim - front right side (Materialabtrag optisch gering) - Scratched - Loss in value



Damage #3: Wheel / tyres: Alloy rim - front left side (Materialabtrag optisch gering) - Scratched - Loss in value



Damage #3: Wheel / tyres: Alloy rim - front left side (Materialabtrag optisch gering) - Scratched - Loss in value



Damage #4: Wheel / tyres: Alloy rim - rear right side (Materialabtr... optisch gering) - Scratched - Loss in value



Damage #4: Wheel / tyres: Alloy rim - rear right side (Materialabtrag optisch gering) - Scratched - Loss in value



Damage #4: Wheel / tyres: Alloy rim - rear right side (Materialabtr... optisch gering) - Scratched - Loss in value



Damage #5: Sill - right side: Trim - Scratched - Repair and paint



Damage #5: Sill - right side: Trim - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 28 May 2025
Protocol number: 40022124



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #7: Misc.: Inspection / maintenance - Due - Replace