



WBA11DZ000FK51395

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	91,545 km
Manufacturer	BMW	Next maintenance in	9,000 km
Type / Model	320d	Main inspection (Report on hand)	10/2025
Vehicle Identification number	WBA11DZ000FK51395	Power / Engine displacement	140 kW / 1,995 ccm
First registration	10 Nov 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Fuel system	Tank cap - Scratched - Smart repair
2	Seat - front	Seat - right side - Scratched - Loss in value
3	Trim / covers	Door trim - front right side - Scratched - Loss in value
4	Trim / covers	Door trim - rear right side - Scratched - Loss in value
5	2nd wheel set	1 alloy rim - Scratched - Loss in value
6	Side panel - rear right side	Sill - Scratched - Smart repair
7	Sill - left side	Trim - Scratched - Paint
8	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Repair and paint
9	Vehicle glazing	Windscreen - Stone chips - Replace
10	Door - rear left side	Door - Scratched - Paint
11	Mudguard - right side	Mudguard - right side - Broken / torn - Replace
12	Side panel - rear left side	Side panel - Scratched - Paint
13	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
14	Steering system	Steering wheel sheath - Broken / torn - Replace
15	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
16	Door - front left side	Door - Scratched - Repair and paint
17	Door - front right side	Door - Scratched - Repair and paint
18	Rear bumper	Rear bumper - Damaged - Replace
19	Front bumper	Front bumper - Damaged - Replace



Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Wheel / tyres	Tyres - complete set - Worn - No deduction
4	Trim / covers	Boot lid - interior trim - Scratched - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Rear, Provided by user / customer

Detected repainting

No.	Location
1	Bumper rear, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	3mm - 3mm	Not o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	3mm - 3mm	Not o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	
2	225/50 R17 98Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 19 May 2025

Protocol number: 39796669

Delivery date: 19 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	320d	Mileage (Read)	91,545 km
Vehicle Identification number	WBA11DZ000FK51395	First registration	10 Nov 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.





Figure 21: Misc.

Pictures of damage



Damage #1: Fuel system: Tank cap - Scratched - Smart repair



Damage #1: Fuel system: Tank cap - Scratched - Smart repair



Damage #2: Seat - front: Seat - right side - Scratched - Loss in value



Damage #2: Seat - front: Seat - right side - Scratched - Loss in value



Damage #3: Trim / covers: Door trim - front right side - Scratched - Loss in value



Damage #3: Trim / covers: Door trim - front right side - Scratched - Loss in value



Damage #4: Trim / covers: Door trim - rear right side - Scratched - Loss in value




Damage #4: Trim / covers: Door trim - rear right side - Scratched - Loss in value




Damage #5: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #5: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #6: Side panel - rear right side: Sill - Scratched - Smart repair




Damage #6: Side panel - rear right side: Sill - Scratched - Smart repair



Damage #6: Side panel - rear right side: Sill - Scratched - Smart repair



Damage #7: Sill - left side: Trim - Scratched - Paint



Damage #7: Sill - left side: Trim - Scratched - Paint



Damage #8: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #8: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #8: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #9: Vehicle glazing: Windscreen - Stone chips - Replace




Damage #10: Door - rear left side: Door - Scratched - Paint



Damage #10: Door - rear left side: Door - Scratched - Paint



Damage #10: Door - rear left side: Door - Scratched - Paint




Damage #11: Mudguard - right side: Mudguard - right side - Broken / torn - Replace



Damage #11: Mudguard - right side: Mudguard - right side - Broken / torn - Replace




Damage #12: Side panel - rear left side: Side panel - Scratch... - Paint



Damage #12: Side panel - rear left side: Side panel - Scratched - Paint



Damage #12: Side panel - rear left side: Side panel - Scratch... - Paint



Damage #12: Side panel - rear left side: Side panel - Scratched - Paint




Damage #13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #14: Steering system: Steering wheel sheath - Broken / torn - Replace



Damage #13: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #14: Steering system: Steering wheel sheath - Broken / torn - Replace



Damage #14: Steering system: Steering wheel sheath - Broken / torn - Replace



Damage #14: Steering system: Steering wheel sheath - Broken / torn - Replace




Damage #15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage #15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage #15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage #15: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage #16: Door - front left side: Door - Scratched - Repair and paint



Damage #16: Door - front left side: Door - Scratched - Repair and paint



Damage #16: Door - front left side: Door - Scratched - Repair and paint



Damage #17: Door - front right side: Door - Scratched - Repair and paint



Damage #16: Door - front left side: Door - Scratched - Repair and paint



Damage #17: Door - front right side: Door - Scratched - Repair and paint




Damage #17: Door - front right side: Door - Scratched - Repair and paint



Damage #18: Rear bumper: Rear bumper - Damaged - Replace




Damage #18: Rear bumper: Rear bumper - Damaged - Replace



Damage #18: Rear bumper: Rear bumper - Damaged - Replace



Damage #18: Rear bumper: Rear bumper - Damaged - Replace



Damage #18: Rear bumper: Rear bumper - Damaged - Replace




Damage #18: Rear bumper: Rear bumper - Damaged - Replace



Damage #19: Front bumper: Front bumper - Damaged - Replace



Damage #19: Front bumper: Front bumper - Damaged - Replace




Damage #19: Front bumper: Front bumper - Damaged - Replace



Damage #19: Front bumper: Front bumper - Damaged - Replace



Damage #19: Front bumper: Front bumper - Damaged - Replace



Damage #19: Front bumper: Front bumper - Damaged - Replace

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 19 May 2025
Protocol number: 39796669
Delivery date: 19 May 2025



Damage #19: Front bumper: Front bumper - Damaged - Replace