




PROTOCOL NUMBER: 37305081



If you have any questions, please state the protocol number and date


Date: 3 Dec 2024

Expert report

Subject	Vorabbesichtigung
Order from	Allane Mobility Consulting GmbH
Inspection date / location	2 Dec 2024 / Allane Mobility Consulting GmbH 69190 Walldorf
Vehicle Identification Number	WAUZZZGB2PR060759



PROTOCOL NUMBER: 37305081



If you have any questions, please state the protocol number and date


Date: 3 Dec 2024

Expert report

Subject	Vorabbesichtigung
Order from	Allane Mobility Consulting GmbH
Inspection date / location	2 Dec 2024 / Allane Mobility Consulting GmbH 69190 Walldorf
Type of vehicle	Passenger Car
Manufacturer	Audi
Model / sales designation	A1 Sportback
Manufacturer key numbers / type code numbers	0588 BVF 01234
Vehicle Identification Number	WAUZZZGB2PR060759
Number of owners	Unknown
First registration	14 Jun 2023
Next periodical technical inspection	06/2026
Vehicle documents	At the time of the inspection, the registration certificate part 1 (license) was available, but the registration certificate part 2 (letter) was not available. ZB Part 1 (certificate) not accepted
Vehicle registration number	License plate not accepted
Mileage	11,630 km / Read
Fuel type	Petrol
Engine displacement / power	999 ccm/ 81 kW
Cylinder / emissions class	/ EURO6;WLTP;AP;PI/CI; M, N1 I
Empty weight (kg)	1,180
Permitted total weight (kg)	1,655
Dimensions (L/W/H)	4035 x 1740 x 1425
Gearbox	Manual



PROTOCOL NUMBER: 37305081



If you have any questions, please state the protocol number and date

Date: 3 Dec 2024

Upholstery / colour	/
Number of keys	1 from 2 Keys available
Maintenance booklet / proof of maintenance	Non-existent
Next maintenance in	18,400 km
Test drive	Not performed
Previous damage	None detectable
Repainting	None detectable

Tyre / wheel rim

Axle / Size	Manufacturer	Tyres	Tread pattern [mm]
#1 185/65 R15 92T	Dunlop	Winter tyres on Light alloy	8 / 8
#2 185/65 R15 92T	Dunlop	Winter tyres on Light alloy	8 / 8

admissibility of wheels All axles permissible

Road Safety Wheels Roadworthy

The wear and tear condition and possible damages to the tyres are considered in the value.

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Rear bumper	Rear bumper - Scratched - Smart repair
3	Bonnet	Bonnet - Dent(s) - Smooth repair work
4	Roof	Roof - Dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction



Notes on expert report

Details of order and scope of evaluation:

An order was placed to perform a vehicle evaluation for the vehicle described.

Vehicle identification:

- The vehicle identification number (VIN) was read and its conformity with the documents submitted was verified during the inspection by the undersigned.

Inspection conditions:

- A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be guaranteed to be sufficient for an assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.
- There were no lifting devices or pits available to examine the vehicle. For this reason, inspection of the underside of the vehicle was only possible to a limited extent.

Test drive / test run of engine and power units:

- No test drive/maneuvering was carried out during the inspection of the vehicle.
- An engine test run was performed.

Previous damages:


- Neither repaired nor non-repaired previous damage to the vehicle could be determined.

Further notes and findings:

- The findings do not include a vehicle inspection as per road traffic regulations [German: StVZO] nor a vehicle inspection as per warranty law [German: Gewährleistungsrecht].
- If damage or defects are only discovered during disassembly/diagnosis work or through advanced knowledge, or are caused by concealed defects or fraudulent deception, please notify the expert



PROTOCOL NUMBER: 37305081



Auto Plus

If you have any questions, please state the protocol number and date

Date: 3 Dec 2024

immediately.

In this case, the technical expert shall have to promptly re-inspect the vehicle to determine the scope of extra repair work and determine the extra cost involved. Those replacement parts that had caused the re-inspection shall be stored until the technical expert has completed the re-inspection.

Comments

Keine Gewähr auf Vollständigkeit und Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden

Fahrzeug ohne 2. Radsatz bewertet. Verschleiß oder Mängel an diesem können nicht ausgeschlossen werden.

Attachments: 17 Overview pictures, 8 Pictures of damage

PROTOCOL NUMBER: 37305081



Auto Plus

Date: 3 Dec 2024

If you have any questions, please state the protocol number and date

Overview pictures



Figure 1: Diagonal front




Figure 2: Diagonal front



Figure 3: Diagonal rear




Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior



PROTOCOL NUMBER: 37305081



Date: 3 Dec 2024

If you have any questions, please state the protocol number and date



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.





Figure 11: Misc.



Figure 12: Misc.

PROTOCOL NUMBER: 37305081



Auto Plus

If you have any questions, please state the protocol number and date

Date: 3 Dec 2024



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




PROTOCOL NUMBER: 37305081



If you have any questions, please state the protocol number and date

Date: 3 Dec 2024

Pictures of damage




Damage 2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Bonnet: Bonnet - Dent(s) - Smooth repair work



Damage 3: Bonnet: Bonnet - Dent(s) - Smooth repair work




Damage 3: Bonnet: Bonnet - Dent(s) - Smooth repair work



Damage 4: Roof: Roof - Dent(s) - Smooth repair work



PROTOCOL NUMBER: 37305081



If you have any questions, please state the protocol number and date

Date: 3 Dec 2024



Damage 4: Roof: Roof - Dent(s) - Smooth repair work



Damage 4: Roof: Roof - Dent(s) - Smooth repair work