

WBY8P210007F73482

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	87,450 km
Manufacturer	BMW	Next maintenance in	-3 Monat(e)
Type / Model	i3	Main inspection (Read from ZBI)	02/2023
Vehicle Identification number	WBY8P210007F73482	Power / Engine displacement	75 kW
First registration	21 Feb 2020	Upholstery/Colour	/
Last maintenance	12/2022, 35,222 km	Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
2	Documents	Log book (Fehlt) - Replace
3	Braking system	Brake fluid - Due - Replace
4	Wing mirror - right side	Cap - Scratched - Loss in value
5	2nd wheel set	1 alloy rim - Scratched - Loss in value
6	Misc.	Main inspection - Due - Replace
7	2nd wheel set	1 tyre - Damaged - Replace
8	Misc.	Inspection / maintenance - Due - Replace
9	Mudguard - right side	Mudguard - right side - Scratched - Repair and paint
10	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace
11	Rear bumper	Rear bumper - Scratched - Repair and paint
12	Side panel - rear right side	Side panel - Scratched - Repair and paint
13	Front bumper	Front bumper - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Wing mirror - right side	Mirror housing - Scratched - Loss in value

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Side right, Provided by user / customer

Detected repainting

No.	Location
	None detectable

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	155/70 R19 84T	Goodyear	Winter tyres	7mm - 7mm	o.k.	
2	155/70 R19 84T	Goodyear	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	155/70 R19 84Q	Bridgestone	Summer tyres	5mm - 5mm	Not o.k.	
2	175/60 R19 86Q	Bridgestone	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 14 Mar 2025
Protocol number: 38848635
Delivery date: 14 Mar 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	i3	Mileage (Read)	87,450 km
Vehicle Identification number	WBY8P210007F73482	First registration	21 Feb 2020

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction



Damage #1: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction



Damage #3: Braking system: Brake fluid - Due - Replace



Damage #4: Wing mirror - right side: Cap - Scratched - Loss in value



Damage #5: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #5: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #5: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #7: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #7: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #8: Misc.: Inspection / maintenance - Due - Replace



Damage #9: Mudguard - right side: Mudguard - right side - Scratched - Repair and paint




Damage #9: Mudguard - right side: Mudguard - right side - Scratched - Repair and paint



Damage #10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage #10: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace




Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #12: Side panel - rear right side: Side panel - Scratched - Repair and paint




Damage #12: Side panel - rear right side: Side panel - Scratched - Repair and paint




Damage #12: Side panel - rear right side: Side panel - Scratched - Repair and paint



Damage #13: Front bumper: Front bumper - Damaged - Replace



Damage #13: Front bumper: Front bumper - Damaged - Replace



Damage #13: Front bumper: Front bumper - Damaged - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 14 Mar 2025
Protocol number: 38848635
Delivery date: 14 Mar 2025



Auto Plus



Damage #13: Front bumper: Front bumper - Damaged - Replace



Damage #13: Front bumper: Front bumper - Damaged - Replace



Damage #13: Front bumper: Front bumper - Damaged - Replace