



WAUZZZF52MA024401

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	163,042 km
Manufacturer	Audi	Next maintenance in	9 Tag(e)
Type / Model	A5 40 TFSI S tronic Sportback Schräghecklimousine5-türig	Main inspection	
Vehicle Identification number	WAUZZZF52MA024401	Power / Engine displacement	/ 1,984 ccm
First registration	22 Jan 2021	Upholstery/Colour	Cloth / Black
Last maintenance		Paintwork	Black
Fuel type	Petrol	Gearbox	

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
2	Rear bumper	Rear bumper - Scratched - Smart repair
3	Boot lid / rear door	Boot lid - Scratched - Smart repair
4	Door - front left side	Door edge - Scratched - Smart repair
5	Door - rear right side	Door - Scratched - Repair and paint
6	Side panel - rear right side	Side panel - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
		The vehicle shows traces of wear and tear corresponding to its age and purpose

Missing parts

Missing part

Detected repainting

No.	Location
1	Boot lid / rear door, Side panel - rear right side, Bumper rear, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98V	Falken	Winter tyres	5mm - 5mm	o.k.	o.k.
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	o.k.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39047041



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94Y	Dunlop	Summer tyres	4mm - 4mm	o.k.	o.k.
2	225/50 R17 98Y	Dunlop	Summer tyres	6mm - 6mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Keine Gewähr auf Vollständigkeit und Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39047041



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A5 40 TFSI S tronic Sportback Schräghecklimousine5-türig	Mileage (Read)	163,042 km
Vehicle Identification number	WAUZZZF52MA024401	First registration	22 Jan 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior




Figure 12: Interior




Figure 13: VIN



Figure 14: Accessories




Figure 15: Accessories



Figure 16: Accessories




Figure 17: Documents



Figure 18: Mounted tyres



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.

Pictures of damage




Damage #1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage #2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #2: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #3: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage #3: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage #4: Door - front left side: Door edge - Scratched - Smart repair



Damage #4: Door - front left side: Door edge - Scratched - Smart repair




Damage #5: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Door - rear right side: Door - Scratched - Repair and paint



Damage #6: Side panel - rear right side: Side panel - Scratch... - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39047041



Auto Plus



Damage #6: Side panel - rear right side: Side panel - Scratched - Repair and paint



Damage #6: Side panel - rear right side: Side panel - Scratch... - Repair and paint