



WAUZZZFY8L2117894

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	102,872 km
Manufacturer	Audi	Next maintenance in	8,700 km
Type / Model	Q5 50 TFSI e	Main inspection (Read from ZBI)	10/2025
Vehicle Identification number	WAUZZZFY8L2117894	Power / Engine displacement	185 kW / 1,984 ccm
First registration	4 Nov 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book - No evidence
2	Door - front left side	Door edge - Scratch(es) - Cover / polish
3	Boot lid / rear door	Boot lid - Scratch(es) - Cover / polish
4	Documents	Main inspection certificate (fehlt) - Replace
5	Seat - front	Seat base trim - right side - Scratched - Loss in value
6	Roof	Roof rail - left side - dent(s) - Smooth repair work
7	Seat - front	Seat base trim - left side - Scratched - Loss in value
8	Side panel - rear left side	Sill - dent(s) - Smart repair
9	Trim / covers	Boot lid - interior trim - Scratched - Replace
10	Mudguard - left side	Wheel arch - Scratched - Paint
11	Rear bumper	Rear bumper - Scratched - Paint
12	Front bumper	Front bumper - Scratched - Paint
13	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front (Winter) - Worn - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 20 Mar 2025
Protocol number: 38947585
Delivery date: 20 Mar 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/65 R17 104H	Michelin	Winter tyres	3mm - 3mm	o.k.	
2	235/65 R17 104H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101W	Michelin	Summer tyres	5mm - 5mm	o.k.	
2	235/55 R19 101W	Michelin	Summer tyres	3mm - 3mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					09/2025

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 20 Mar 2025
Protocol number: 38947585
Delivery date: 20 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q5 50 TFSI e	Mileage (Read)	102,872 km
Vehicle Identification number	WAUZZZFY8L2117894	First registration	4 Nov 2020

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front




Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 20 Mar 2025
Protocol number: 38947585
Delivery date: 20 Mar 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 20 Mar 2025
Protocol number: 38947585
Delivery date: 20 Mar 2025




Auto Plus



Figure 25: Misc.

Pictures of damage




Damage #2: Door - front left side: Door edge - Scratch(es) - Cover / polish



Damage #2: Door - front left side: Door edge - Scratch(es) - Cover / polish




Damage #3: Boot lid / rear door: Boot lid - Scratch(es) - Cover / polish



Damage #3: Boot lid / rear door: Boot lid - Scratch(es) - Cover / polish




Damage #5: Seat - front: Seat base trim - right side - Scratched - Loss in value



Damage #6: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage #6: Roof: Roof rail - left side - dent(s) - Smooth repair work




Damage #6: Roof: Roof rail - left side - dent(s) - Smooth repair work




Damage #7: Seat - front: Seat base trim - left side - Scratched - Loss in value



Damage #7: Seat - front: Seat base trim - left side - Scratched... Loss in value



Damage #8: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage #8: Side panel - rear left side: Sill - dent(s) - Smart repair



Damage #9: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage #9: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage #10: Mudguard - left side: Wheel arch - Scratched - Paint



Damage #10: Mudguard - left side: Wheel arch - Scratched - Paint



Damage #11: Rear bumper: Rear bumper - Scratched - Paint



Damage #11: Rear bumper: Rear bumper - Scratched - Paint



Damage #11: Rear bumper: Rear bumper - Scratched - Paint



Damage #11: Rear bumper: Rear bumper - Scratched - Paint




Damage #12: Front bumper: Front bumper - Scratched - Paint



Damage #12: Front bumper: Front bumper - Scratched - Paint



Damage #12: Front bumper: Front bumper - Scratched - Paint



Damage #12: Front bumper: Front bumper - Scratched - Paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 20 Mar 2025
Protocol number: 38947585
Delivery date: 20 Mar 2025



Auto Plus



Damage #13: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #13: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #13: Mudguard - left side: Mudguard - left side - De... paintcoat damage - Repair and paint