



WAUZZZF4L2100722

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	42,113 km
Manufacturer	Audi	Next maintenance in	15,100 km
Type / Model	Q5 50 TFSI e S tronic quattro Sports Utility Vehicle5-türig 1984 ccm 299 PS / 220 KW Elektrisch 7-Gang Automatik	Main inspection	
Vehicle Identification number	WAUZZZF4L2100722	Power / Engine displacement	/ 1,984 ccm
First registration	6 Oct 2020	Upholstery/Colour	Cloth / Black
Last maintenance		Paintwork	White
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - front right side	Brightware - lower - Scratched - Replace
2	Door - rear right side	Brightware - lower - Scratched - Replace
3	Front bumper	Front bumper - Scratched - Paint
4	Door - rear right side	Door - Scratched - Repair and paint
5	Door - front right side	Door - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R18 107H	Dunlop	Winter tyres	5mm - 5mm	o.k.	o.k.
2	235/60 R18 107H	Dunlop	Winter tyres	6mm - 6mm	o.k.	o.k.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39003972



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R18 103V	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.
2	235/60 R18 103W	Michelin	Summer tyres	6mm - 6mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39003972



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	Q5 50 TFSI e S tronic quattro Sports Utility Vehicle5-türig 1984 ccm 299 PS / 220 KW Elektrisch 7-Gang Automatik	Mileage (Read)	42,113 km
Vehicle Identification number	WAUZZZFY4L2100722	First registration	6 Oct 2020

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39003972



Auto Plus



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior



Figure 12: VIN



Figure 13: Accessories



Figure 14: Accessories



Figure 15: Accessories




Figure 16: Documents



Figure 17: Mounted tyres



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.

Pictures of damage



Damage #1: Door - front right side: Brightware - lower - Scratched - Replace



Damage #1: Door - front right side: Brightware - lower - Scratched - Replace



Damage #2: Door - rear right side: Brightware - lower - Scratched - Replace



Damage #2: Door - rear right side: Brightware - lower - Scratched - Replace



Damage #3: Front bumper: Front bumper - Scratched - Paint




Damage #3: Front bumper: Front bumper - Scratched - Paint




Damage #3: Front bumper: Front bumper - Scratched - Paint




Damage #3: Front bumper: Front bumper - Scratched - Paint



Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Door - front right side: Door - Scratched - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 25 Mar 2025
Protocol number: 39003972



Auto Plus



Damage #5: Door - front right side: Door - Scratched - Repair and paint