



WBA5P51090FK80637

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	86,405 km
Manufacturer	BMW	Next maintenance in	7 Monat(e)
Type / Model	330e Advantage Automatik Limousine4-türig	Main inspection	
Vehicle Identification number	WBA5P51090FK80637	Power / Engine displacement	/ 1,998 ccm
First registration	7 Jan 2021	Upholstery/Colour	Cloth / leather combination / Black
Last maintenance		Paintwork	Black
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Door - front left side	Door edge - Scratched - Smart repair
4	Mudguard - left side	Mudguard - left side - Scratched - Smart repair
5	Door - rear left side	Door edge - Scratched - Smart repair
6	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	o.k.
2	225/50 R17 98V	Michelin	Winter tyres	6mm - 6mm	o.k.	o.k.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 4 Apr 2025
Protocol number: 39187659



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.
2	225/50 R17 98Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 4 Apr 2025
Protocol number: 39187659



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	330e Advantage Automatik Limousine4-türig	Mileage (Read)	86,405 km
Vehicle Identification number	WBA5P51090FK80637	First registration	7 Jan 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: VIN



Figure 14: Accessories



Figure 15: Accessories




Figure 16: Documents



Figure 17: Mounted tyres



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.


Pictures of damage



Damage #1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage #3: Door - front left side: Door edge - Scratched - Smart repair



Damage #4: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage #4: Mudguard - left side: Mudguard - left side - Scratche... Smart repair



Damage #5: Door - rear left side: Door edge - Scratched - Smart repair

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 4 Apr 2025
Protocol number: 39187659



Auto Plus



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint