



WF0PXXGCHPMJ31100

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	73,097 km
Manufacturer	Ford	Next maintenance in	11 Monat(e)
Type / Model	Focus	Main inspection (Report not on hand)	03/2026
Vehicle Identification number	WF0PXXGCHPMJ31100	Power / Engine displacement	92 kW / 999 ccm
First registration	1 Apr 2021	Upholstery/Colour	/
Last maintenance	03/2024, 52,295 km	Paintwork	
Fuel type	Hybrid Petrol / E	Gearbox	Manual

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Documents	Main inspection certificate (Fehlt) - Replace
3	Rear axle	Wheel bearing - right side - Specify findings - Perform diagnosis
4	Vehicle glazing	Windscreen - Stone chips - Replace
5	Rear bumper	Rear bumper - Scratched - Repair and paint
6	Boot lid / rear door	Rear spoiler - Dent / paintcoat damage - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 92H	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	205/60 R16 92H	Goodyear	Winter tyres	8mm - 8mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 3 Apr 2025

Protocol number: 39162307

Delivery date: 3 Apr 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 92V	Goodyear	Summer tyres	3mm - 3mm	o.k.	
2	205/60 R16 92V	Goodyear	Summer tyres	4mm - 4mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					02/2025

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 3 Apr 2025
Protocol number: 39162307
Delivery date: 3 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Ford	Inspection condition	Sufficient
Type / Model	Focus	Mileage (Read)	73,097 km
Vehicle Identification number	WF0PXXGCHPMJ31100	First registration	1 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 3 Apr 2025
Protocol number: 39162307
Delivery date: 3 Apr 2025



Auto Plus



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior




Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.




Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.


Pictures of damage



Damage #3: Rear axle: Wheel bearing - right side - Specify findin...
- Perform diagnosis



Damage #4: Vehicle glazing: Windscreen - Stone chips -
Replace




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and
paint



Damage #5: Rear bumper: Rear bumper - Scratched - Repair and
paint



Damage #5: Rear bumper: Rear bumper - Scratched - Repair and
paint



Damage #6: Boot lid / rear door: Rear spoiler - Dent / paintcoat
damage - Replace


TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 3 Apr 2025
Protocol number: 39162307
Delivery date: 3 Apr 2025



Damage #6: Boot lid / rear door: Rear spoiler - Dent / paintcoat damage - Replace



Damage #6: Boot lid / rear door: Rear spoiler - Dent / paintcoat damage - Replace