



WBA7K310005R39920

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	20,453 km
Manufacturer	BMW	Next maintenance in	26,000 Monat(e)
Type / Model	118i	Main inspection (Report on hand)	01/2027
Vehicle Identification number	WBA7K310005R39920	Power / Engine displacement	103 kW / 1,499 ccm
First registration	4 Mar 2020	Upholstery/Colour	/
Last maintenance	01/2025, 16,652 km	Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Paint defect - Cover / polish
2	Rear bumper	Spoiler - Scratched - Loss in value
3	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
4	Door - front left side	Door - Dent / paintcoat damage - Smart repair
5	Door - rear right side	Door - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R17 94Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	
2	225/45 R17 94Y	Goodyear	Summer tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 15 Apr 2025
Protocol number: 39326580
Delivery date: 15 Apr 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91H	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	205/55 R16 91H	Pirelli	Winter tyres	7mm - 7mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 15 Apr 2025
Protocol number: 39326580
Delivery date: 15 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	118i	Mileage (Read)	20,453 km
Vehicle Identification number	WBA7K310005R39920	First registration	4 Mar 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 15 Apr 2025
Protocol number: 39326580
Delivery date: 15 Apr 2025



Auto Plus




Figure 19: Misc.




Figure 20: Misc.

Pictures of damage



Damage #1: Rear bumper: Rear bumper - Paint defect - Cover / polish



Damage #1: Rear bumper: Rear bumper - Paint defect - Cover / polish




Damage #1: Rear bumper: Rear bumper - Paint defect - Cover / polish



Damage #2: Rear bumper: Spoiler - Scratched - Loss in value



Damage #2: Rear bumper: Spoiler - Scratched - Loss in value




Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage #4: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage #4: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage #4: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage #5: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Door - rear right side: Door - Scratched - Repair and paint