



WBA31BN070CG47752

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	107,611 km
Manufacturer	BMW	Next maintenance in	17,000 km
Type / Model	520d	Main inspection (Report on hand)	09/2026
Vehicle Identification number	WBA31BN070CG47752	Power / Engine displacement	140 kW / 1,995 ccm
First registration	4 Feb 2021	Upholstery/Colour	/
Last maintenance	11/2024, 99,268 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - Repair and paint
2	Front bumper	Front bumper - Scratched - Repair and paint
3	Side panel - rear left side	Side panel - Scratched - Repair and paint
4	Bonnet	Bonnet - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Steering system	Steering wheel - Scratched - No deduction
2	Vehicle glazing	Windscreen (Steinschläge) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Rear, Provided by user / customer

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Mar 2025

Protocol number: 39061455

Delivery date: 28 Mar 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 97H	Pirelli	Winter tyres	4mm - 4mm	o.k.	
2	225/55 R17 97H	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101Y	Goodyear	Summer tyres	6mm - 6mm	o.k.	
2	225/55 R17 101Y	Goodyear	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Mar 2025
Protocol number: 39061455
Delivery date: 28 Mar 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	520d	Mileage (Read)	107,611 km
Vehicle Identification number	WBA31BN070CG47752	First registration	4 Feb 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Mar 2025
Protocol number: 39061455
Delivery date: 28 Mar 2025





Figure 25: Misc.

Pictures of damage



Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Front bumper: Front bumper - Scratched - Repair and paint



Damage #2: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Side panel - rear left side: Side panel - Scratched - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Mar 2025
Protocol number: 39061455
Delivery date: 28 Mar 2025



Auto Plus



Damage #3: Side panel - rear left side: Side panel - Scratched - Repair and paint



Damage #4: Bonnet: Bonnet - Scratched - Paint



Damage #4: Bonnet: Bonnet - Scratched - Paint