



WBA41FY020FN56763

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	17,687 km
Manufacturer	BMW	Next maintenance in	5 Monat(e)
Type / Model	320e	Main inspection (Read from ZBI)	10/2025
Vehicle Identification number	WBA41FY020FN56763	Power / Engine displacement	120 kW / 1,998 ccm
First registration	18 Oct 2022	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - Scratched - Cover / polish
2	Rear bumper	Rear bumper - Scratched - Cover / polish
3	Wing mirror - right side	Cap - Scratched - Smart repair
4	Wing mirror - left side	Cap - Scratched - Smart repair
5	Boot lid / rear door	Boot lid - Scratched - Smart repair
6	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Body	Body - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39497280
Delivery date: 28 Apr 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Bridgestone	Summer tyres	6mm - 6mm	o.k.	
2	225/50 R17 98Y	Bridgestone	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39497280
Delivery date: 28 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	320e	Mileage (Read)	17,687 km
Vehicle Identification number	WBA41FY020FN56763	First registration	18 Oct 2022

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39497280
Delivery date: 28 Apr 2025



Auto Plus



Figure 7: Interior




Figure 8: Interior




Figure 9: Interior




Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.




Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.





Figure 23: Misc.

Pictures of damage




Damage #1: Side panel - rear right side: Side panel - Scratched - Cover / polish



Damage #1: Side panel - rear right side: Side panel - Scratch... - Cover / polish




Damage #2: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage #2: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage #3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage #3: Wing mirror - right side: Cap - Scratched - Smart repair



Damage #4: Wing mirror - left side: Cap - Scratched - Smart repair



Damage #4: Wing mirror - left side: Cap - Scratched - Smart repair



Damage #5: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage #5: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39497280
Delivery date: 28 Apr 2025




Auto Plus



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint