



WBA5P51090FL19744

Vehicle details

Operator		Inspection condition	conditional: sufficient
License number		Mileage (Read)	95,023 km
Manufacturer	BMW	Next maintenance in	9,000 km
Type / Model	330e	Main inspection (Read from ZBI)	04/2026
Vehicle Identification number	WBA5P51090FL19744	Power / Engine displacement	135 kW / 1,998 ccm
First registration	8 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
3	Wing mirror - right side	Cap - Scratched - Paint
4	2nd wheel set	2 alloy rims - Scratched - Loss in value
5	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
6	Front bumper	Front bumper - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025

Protocol number: 39483573

Delivery date: 28 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Michelin	Winter tyres	5mm - 5mm	o.k.	o.k.
2	225/45 R18 95V	Michelin	Winter tyres	5mm - 5mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R19 93Y	Pirelli	Summer tyres	3mm - 3mm	o.k.	
2	255/35 R19 96Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39483573
Delivery date: 28 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: sufficient
Type / Model	330e	Mileage (Read)	95,023 km
Vehicle Identification number	WBA5P51090FL19744	First registration	8 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were only partially sufficient for assessing the vehicle. At the time of the inspection, it could not be ensured that the condition was sufficient for an adequate assessment. The expert therefore recommends a further inspection to reduce the risk of prognosis.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior




Figure 7: Interior




Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39483573
Delivery date: 28 Apr 2025



Figure 19: Misc.



Figure 20: Misc.


Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - No deduction



Damage #1: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction



Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage #3: Wing mirror - right side: Cap - Scratched - Paint



Damage #3: Wing mirror - right side: Cap - Scratched - Paint



Damage #4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #4: 2nd wheel set: 2 alloy rims - Scratched - Loss in value




Damage #5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #5: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #6: Front bumper: Front bumper - Damaged - Replace



Damage #6: Front bumper: Front bumper - Damaged - Replace



Damage #6: Front bumper: Front bumper - Damaged - Replace



Damage #6: Front bumper: Front bumper - Damaged - Replace