



WAUZZZGE6RB062813

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	12,674 km
Manufacturer	Audi	Next maintenance in	17,400 km
Type / Model	Q8 50 e-tron	Main inspection (Read from ZBI)	07/2027
Vehicle Identification number	WAUZZZGE6RB062813	Power / Engine displacement	158 kW
First registration	8 Jul 2024	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Wheel well extension - Scratched - Smart repair
2	Rear bumper	Rear bumper - Scratched - Repair and paint
3	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/55 R19 111H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	255/55 R19 111H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 May 2025
Protocol number: 39581025
Delivery date: 6 May 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/50 R20 109H	Bridgestone	Summer tyres	7mm - 7mm	o.k.	
2	255/50 R20 109H	Bridgestone	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 May 2025
Protocol number: 39581025
Delivery date: 6 May 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q8 50 e-tron	Mileage (Read)	12,674 km
Vehicle Identification number	WAUZZZGE6RB062813	First registration	8 Jul 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior




Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.


Pictures of damage




Damage #1: Side panel - rear left side: Wheel well extension - Scratched - Smart repair




Damage #1: Side panel - rear left side: Wheel well extension - Scratched - Smart repair



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 May 2025
Protocol number: 39581025
Delivery date: 6 May 2025



Auto Plus



Damage #3: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Front bumper: Front bumper - Scratched - Repair and paint