



WAUZZZF27PN031279

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	37,403 km
Manufacturer	Audi	Next maintenance in	8,700 km
Type / Model	A6 Avant 50 TFSI e	Main inspection (Read from ZBI)	12/2025
Vehicle Identification number	WAUZZZF27PN031279	Power / Engine displacement	195 kW / 1,984 ccm
First registration	28 Dec 2022	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Smart repair
2	Front bumper	Spoiler - Scratched - Smart repair
3	Side panel - rear left side	Sill - Scratched - Smart repair
4	Door - rear right side	Door - Scratched - Repair and paint
5	Vehicle glazing	Windscreen - Stone chips - Replace
6	Rear bumper	Rear bumper - Scratched - Paint
7	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
8	Side panel - rear right side	Side panel - Scratched - Paint
9	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 14 Apr 2025
Protocol number: 39317203
Delivery date: 14 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102V	Michelin	Winter tyres	6mm - 6mm	o.k.	
2	225/55 R18 102V	Michelin	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	225/55 R18 102Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					12/2027

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 14 Apr 2025
Protocol number: 39317203
Delivery date: 14 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A6 Avant 50 TFSI e	Mileage (Read)	37,403 km
Vehicle Identification number	WAUZZZF27PN031279	First registration	28 Dec 2022

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.

Pictures of damage



Damage #1: Front bumper: Front bumper - Scratched - Smart repair



Damage #1: Front bumper: Front bumper - Scratched - Smart repair




Damage #2: Front bumper: Spoiler - Scratched - Smart repair



Damage #2: Front bumper: Spoiler - Scratched - Smart repair



Damage #3: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #3: Side panel - rear left side: Sill - Scratched - Smart repair




Damage #4: Door - rear right side: Door - Scratched - Repair and paint




Damage #4: Door - rear right side: Door - Scratched - Repair and paint



Damage #5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #5: Vehicle glazing: Windscreen - Stone chips - Replace




Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint




Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint



Damage #6: Rear bumper: Rear bumper - Scratched - Paint




Damage #6: Rear bumper: Rear bumper - Scratched - Paint




Damage #7: Door - front right side: Door - Dent / paintcoat damage
- Repair and paint



Damage #7: Door - front right side: Door - Dent / paintcoat damage
- Repair and paint



Damage #7: Door - front right side: Door - Dent / paintcoat damage
- Repair and paint



Damage #7: Door - front right side: Door - Dent / paintcoat damage
- Repair and paint



Damage #7: Door - front right side: Door - Dent / paintcoat damage
- Repair and paint



Damage #8: Side panel - rear right side: Side panel - Scratch...
- Paint




Damage #8: Side panel - rear right side: Side panel - Scratched -
Paint



Damage #8: Side panel - rear right side: Side panel - Scratch...
- Paint



Damage #9: Side panel - rear left side: Side panel - Dent /
paintcoat damage - Repair and paint



Damage #9: Side panel - rear left side: Side panel - Dent /
paintcoat damage - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 14 Apr 2025
Protocol number: 39317203
Delivery date: 14 Apr 2025



Auto Plus



Damage #9: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #9: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint