



WAUZZZF57PN002648

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	83,755 km
Manufacturer	Audi	Next maintenance in	-4,100 km
Type / Model	A5 Cabriolet	Main inspection (Read from ZBI)	02/2026
Vehicle Identification number	WAUZZZF57PN002648	Power / Engine displacement	120 kW / 1,968 ccm
First registration	28 Feb 2023	Upholstery/Colour	/
Last maintenance	08/2024, 54,100 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat base trim - right side - Scratched - Loss in value
2	Seat - front	Seat base trim - left side - Scratched - Loss in value
3	2nd wheel set	1 alloy rim - Scratched - Loss in value
4	2nd wheel set	2 tyres - Worn - Replace
5	Misc.	Inspection / maintenance - Due - Replace
6	Rear bumper	Rear bumper - Scratched - Repair and paint
7	Front bumper	Front bumper - Scratched - Repair and paint
8	Side panel - rear right side	Side panel - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen (Steinschläge) - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Side panel - rear left side, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98V	Michelin	Winter tyres	6mm - 6mm	o.k.	
2	225/50 R17 98H	Goodyear	Winter tyres	7mm - 7mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39540062
Delivery date: 2 May 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94Y	Hankook	Summer tyres	3mm - 3mm	Not o.k.	
2	225/50 R17 94Y	Hankook	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					10/2026

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39540062
Delivery date: 2 May 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	A5 Cabriolet	Mileage (Read)	83,755 km
Vehicle Identification number	WAUZZZF57PN002648	First registration	28 Feb 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal front



Figure 4: Diagonal rear



Figure 5: Diagonal rear



Figure 6: Diagonal rear



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.


Pictures of damage




Damage #1: Seat - front: Seat base trim - right side - Scratched - Loss in value




Damage #1: Seat - front: Seat base trim - right side - Scratch... - Loss in value



Damage #1: Seat - front: Seat base trim - right side - Scratched - Loss in value



Damage #2: Seat - front: Seat base trim - left side - Scratch... - Loss in value



Damage #2: Seat - front: Seat base trim - left side - Scratched - Loss in value



Damage #3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage #4: 2nd wheel set: 2 tyres - Worn - Replace



Damage #4: 2nd wheel set: 2 tyres - Worn - Replace




Damage #5: Misc.: Inspection / maintenance - Due - Replace



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #7: Front bumper: Front bumper - Scratched - Repair and paint



Damage #7: Front bumper: Front bumper - Scratched - Repair and paint



Damage #7: Front bumper: Front bumper - Scratched - Repair and paint



Damage #8: Side panel - rear right side: Side panel - dent(s) - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39540062
Delivery date: 2 May 2025



Auto Plus



Damage #8: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Damage #8: Side panel - rear right side: Side panel - dent(s) - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Apr 2025
Protocol number: 39540062
Delivery date: 2 May 2025



Auto Plus

Pictures of repainting



Repainting 1: Side panel - rear left side