



WBA2N510807G59800

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	22,954 km
Manufacturer	BMW	Next maintenance in	23,000 km
Type / Model	218d	Main inspection (Report not on hand)	10/2025
Vehicle Identification number	WBA2N510807G59800	Power / Engine displacement	110 kW / 1,995 ccm
First registration	2 Sept 2020	Upholstery/Colour	/
Last maintenance	10/2023, 15,176 km	Paintwork	
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
5	Door - front left side	Door - dent(s) - Smooth repair work
6	2nd wheel set	1 alloy rim - Scratched - Loss in value
7	2nd wheel set	1 tyre - Damaged - Replace
8	Tail light	Tail lamp - right side - Damaged - Replace
9	Front bumper	Front bumper - Scratched - Repair and paint
10	Rear bumper	Rear bumper - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 May 2025

Protocol number: 39800611

Delivery date: 20 May 2025



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R18 92V	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/40 R18 92V	Pirelli	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R17 91W	Bridgestone	Summer tyres	6mm - 6mm	Not o.k.	
2	245/40 R17 91W	Bridgestone	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 May 2025
Protocol number: 39800611
Delivery date: 20 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	218d	Mileage (Read)	22,954 km
Vehicle Identification number	WBA2N510807G59800	First registration	2 Sept 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal front



Figure 4: Diagonal rear



Figure 5: Diagonal rear



Figure 6: Diagonal rear



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.


Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #1: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #4: Bonnet: Insulation lining - Damage caused by marte... rodent - Replace



Damage #5: Door - front left side: Door - dent(s) - Smooth repair work




Damage #5: Door - front left side: Door - dent(s) - Smooth repair work




Damage #6: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #7: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #8: Tail light: Tail lamp - right side - Damaged - Replace



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 May 2025
Protocol number: 39800611
Delivery date: 20 May 2025



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #10: Rear bumper: Rear bumper - Damaged - Replace