



WBA7K310005T26244

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	106,028 km
Manufacturer	BMW	Next maintenance in	-900 km
Type / Model	118i	Main inspection (Report on hand)	03/2026
Vehicle Identification number	WBA7K310005T26244	Power / Engine displacement	100 kW / 1,499 ccm
First registration	1 Mar 2021	Upholstery/Colour	Cloth / Black-Anthracite
Last maintenance		Paintwork	White
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 tyre - Damaged - Replace
2	Misc.	Inspection / maintenance - Due - Perform
3	Gearbox	Gearbox (Ölwechsel überfällig) - Due - Replace
4	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	2nd wheel set	2 alloy rims - Scratched - No deduction
3	Rear bumper	Rear bumper - Scratched - No deduction
4	Trim / covers	Boot lid - interior trim - Scratched - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Door - rear left side, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	195/60 R16 89H	Pirelli	Winter tyres	6mm - 6mm	o.k.	o.k.
2	195/60 R16 89H	Fulda	Winter tyres	7mm - 7mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R17 94Y XL	Goodyear	Summer tyres	5mm - 5mm	o.k.	o.k.
2	225/45 R17 94Y XL	Goodyear	Summer tyres	6mm - 6mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
No navigation unit
Radio DAB

Comments

Keine Fahrzeugunterlagen vorhanden, Fahrzeugdaten der Auftragsunterlagen entnommen. Keine Ausstattungsliste vorhanden. Ausstattung nicht geprüft.

Lackschichtstärke geprüft

Keine Gewähr auf Vollständigkeit und Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten

Die Besichtigung wurde durch den Sachverständigen Michael Weber durchgeführt.
Das Gutachten wurde unparteiisch nach bestem Wissen und Gewissen erstellt.

Fehlende Zubehörteile wie, z.B. Abdeckungen, Räder, Schlüssel, etc. werden bei einer Vorabbewertung, bzw. bei Kaufinteresse Seitens des Nutzers nicht in Abzug gebracht.

Fehlteile müssen bei der Fahrzeugrückgabe vom Nutzer bereitgestellt werden.
Das Fahrzeug muss zur Rückgabe gereinigt werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
-
71679 Asperg

Inspection date: 25 Mar 2025
Protocol number: 39050998



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	118i	Mileage (Read)	106,028 km
Vehicle Identification number	WBA7K310005T26244	First registration	1 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior



Figure 12: Interior



Figure 13: Interior



Figure 14: Interior



Figure 15: Interior




Figure 16: Interior




Figure 17: VIN



Figure 18: VIN



Figure 19: Accessories



Figure 20: Accessories



Figure 21: Accessories




Figure 22: Accessories



Figure 23: Accessories



Figure 24: Accessories

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
-
71679 Asperg

Inspection date: 25 Mar 2025
Protocol number: 39050998



Figure 25: Accessories



Figure 26: Accessories




Figure 27: Accessories



Figure 28: Documents



Figure 29: Documents



Figure 30: Documents



Figure 31: Documents




Figure 32: Documents




Figure 33: Documents



Figure 34: Mounted tyres



Figure 35: Mounted tyres



Figure 36: Mounted tyres



Figure 37: Mounted tyres



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.




Figure 44: Misc.



Figure 45: Misc.

Pictures of damage




Damage #1: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #1: 2nd wheel set: 1 tyre - Damaged - Replace




Damage #2: Misc.: Inspection / maintenance - Due - Perform



Damage #3: Gearbox: Gearbox (Ölwechsel überfällig) - Due - Replace



Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace