



WBY11CF010CK58955

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	100,754 km
Manufacturer	BMW	Next maintenance in	14 Tag(e)
Type / Model	iX xDrive40	Main inspection (Taken from ZBI)	06/2025
Vehicle Identification number	WBY11CF010CK58955	Power / Engine displacement	102 kW
First registration	8 Jun 2022	Upholstery/Colour	/
Last maintenance	06/2024, 46,343 km	Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Interior	Sun visor - left side - Damaged - Replace
2	2nd wheel set	1 alloy rim - Scratched - Loss in value
3	2nd wheel set	1 tyre - Damaged - Replace
4	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
5	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
6	Misc.	Inspection / maintenance - Due - Replace
7	Rear bumper	Rear bumper - Scratched - Paint
8	Front bumper	Front bumper - Deformed - Repair and paint
9	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Sill - left side, Professionally carried out

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 26 May 2025

Protocol number: 39909935

Delivery date: 26 May 2025



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R20 103H	Continental	Winter tyres	7mm - 7mm	o.k.	
2	235/60 R20 103H	Continental	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/50 R21 109Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	
2	255/50 R21 109Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					07/2027

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n .i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 26 May 2025

Protocol number: 39909935

Delivery date: 26 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	iX xDrive40	Mileage (Read)	100,754 km
Vehicle Identification number	WBY11CF010CK58955	First registration	8 Jun 2022

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

Pictures of damage




Damage #1: Interior: Sun visor - left side - Damaged - Replace



Damage #1: Interior: Sun visor - left side - Damaged - Replace



Damage #2: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage #2: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #3: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #3: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage #4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage #4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage #4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage #4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage #5: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #5: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #5: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage #6: Misc.: Inspection / maintenance - Due - Replace



Damage #7: Rear bumper: Rear bumper - Scratched - Paint



Damage #7: Rear bumper: Rear bumper - Scratched - Paint




Damage #7: Rear bumper: Rear bumper - Scratched - Paint




Damage #7: Rear bumper: Rear bumper - Scratched - Paint



Damage #7: Rear bumper: Rear bumper - Scratched - Paint



Damage #7: Rear bumper: Rear bumper - Scratched - Paint



Damage #7: Rear bumper: Rear bumper - Scratched - Paint



Damage #8: Front bumper: Front bumper - Deformed - Repair and paint




Damage #8: Front bumper: Front bumper - Deformed - Repair and paint




Damage #8: Front bumper: Front bumper - Deformed - Repair and paint




Damage #8: Front bumper: Front bumper - Deformed - Repair and paint




Damage #8: Front bumper: Front bumper - Deformed - Repair and paint



Damage #9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage #9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage #9: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 26 May 2025
Protocol number: 39909935
Delivery date: 26 May 2025



Damage #9: Boot lid / rear door: Boot lid - Dent / paintcoat damage
- Repair and paint