

Onderhouds historie
HYUNDAI i20 1.0 T-GDI 100 ActieAuto + Navigatie Comfort HPL



Chassisnummer NLHB351AAJZ381669

Kenteken SF-100-L

Beschrijving	Onderhouden door	Datum	Type	Tellerstand	Kosten
Linkerzijde Spiegel vandalisme	Mitsubishi Ursem Ba	3/16/2021	DAMAGE	0	412,18 €
APK zndr beurt - NVT	Mitsubishi Ursem Ba	3/28/2024	REPAIR	64415	0,00 €
75.000 Km - NVT	Mitsubishi Ursem Ba	6/9/2023	REPAIR	61384	209,69 €
60.000 Km - NVT	Mitsubishi Ursem Ba	5/16/2022	REPAIR	51829	246,29 €
APK zndr beurt - NVT	Mitsubishi Ursem Ba	3/9/2022	REPAIR	48378	11,22 €
Diverse lampjes - Werkt niet	Mitsubishi Ursem Ba	3/9/2022	REPAIR	48378	0,00 €
45.000 Km - NVT	Mitsubishi Ursem Ba	5/7/2021	REPAIR	34736	287,28 €
Luchtfilter - versleten	Mitsubishi Ursem Ba	5/7/2021	REPAIR	34736	0,00 €
Ruitenw.blad A - versleten	Mitsubishi Ursem Ba	5/7/2021	REPAIR	34736	0,00 €
Ruitenw.blad V - versleten	Mitsubishi Ursem Ba	5/7/2021	REPAIR	34736	0,00 €
30.000 Km - NVT	Mitsubishi Ursem Ba	5/14/2020	REPAIR	24721	277,03 €
Int luchtfilter - versleten	Mitsubishi Ursem Ba	5/14/2020	REPAIR	24721	0,00 €
15.000 Km - NVT	Mitsubishi Ursem Ba	4/3/2019	REPAIR	12402	0,00 €