



Brand:	Audi	Mileage(km):	96313
Model:	e-tron	Number of doors:	5
Model type:	e-tron 50 quattro Launch edition plus 71 kWh	Vehicle length (cm):	
License plate:	H860BX	Vehicle width (cm):	
Report code:	4817	Vehicle height (cm):	
Chassis number:	WAUZZZGE6LB014817	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	31/12/2019	Power(kw):	230
First NL reg.:	31/12/2019	Transmission	Automatic
Color:	Grey 🔽 Metallic	Number of gears	
Weight (kg)(kg):	2445	Displacement(cc):	
Empty weight(kg):	2345	Number of cylinders:	
Wheelbase (cm)(cm):	293	Fuel type:	Electric
Top speed (km/h):	190	Fuel tank capacity:	
Cons. in the city (I/100 km):		EU category:	
Cons. outside the city (I/100 km):		Energy label:	Α
Avarage consumption (I/100 km):		NL Tax Rate %:	
Acceleration (s):	7	CO2 (q/km):	
Cargo space (I):	2445	Nb. of Axles:	2
Perm. max weight (kg):	3040	APK date:	31/12/2025

opties

\checkmark	Alloy wheels
$\overline{}$	Leather upholstery
$\overline{}$	Air suspension
~	Digital dashboard
~	Daytime running lights
~	Licht Sensor
~	bots waarschuwing systeem
~	Anti-lock braking system
~	ABS
~	Airbag(s)
~	Audio
~	bots herkenning systeem
~	Central locking system
~	Power steering
~	Front seats adjustable in height
~	Multifunctional steering wheel
~	Remote central locking
~	Roof rail (silver)
Image: A start a st	Metallic finish
Image: A start a st	Panoramic roof (electrical)
~	Sliding / tilting roof (electric)
300000000000000000000000000000000000000	LED headlights
\sim	Headlight washers
	LED rear lights

_	
\leq	Exterior mirrors in car body color
\leq	Privacy glass
<u>~</u>	Rain sensor
≤	Rear wiper
\mathbf{Z}	Rear parking sensors
<	Front parking sensors
\checkmark	Rear-seat folding (equal parts)
~	Rear-seat folding (unequal parts)
~	Luggage cover
~	Charging cable 380V
~	Charging cable 220V
~	iPod connection
~	USB connection
~	Bluetooth streaming
~	Bluetooth car kit
~	Radio
~	WiFi
~	Cruise control (adaptive)
~	Cruise control
~	Airconditioning
~	Airconditioning in the back
~	Climate control
~	Exterior mirrors in car body color Privacy glass Rain sensor Rear wiper Rear parking sensors Front parking sensors Rear-seat folding (equal parts) Rear-seat folding (unequal parts) Luggage cover Charging cable 380V Charging cable 220V iPod connection USB connection Bluetooth streaming Bluetooth streaming Bluetooth car kit Radio WiFi Cruise control (adaptive) Cruise control Airconditioning Airconditioning in the back Climate control (analog)
-	Climate control (digital)

Climate control (L/R separated) Large screen navigation Keyless entry Keyless entry/start/stop Keyless start/stop Electrically constant Keyless start/stop Electrically operated rear w Electrically operated from the electrically folding mirrors Electrically adjustable mirries Electrically adjustable drived Electrically adjustable drived Electrically adjustable drived Electrically heated drivers Electrically heated drivers Electrically heated drivers Electrically heated drivers Electrically heated passeng Central armrest front Adjustable lumbar support Audio control on the steering Leather steering wheel Switch flippers Lane assistance Pedestrian safety system Electrically operated rear windows Electrically operated front windows Electrically folding mirrors Electrically adjustable mirrors Electrically adjustable driver's seat Electrically adjustable driver's seat (including memory) Electrically adjustable passenger seat Electrically heated driver's seat Electrically heated passenger seat Adjustable lumbar support driver's seat Adjustable lumbar support passenger seat Audio control on the steering wheel

¢ Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	265/45 R21	Pirelli	4
Tire left rear	Winter	Alloy	265/45 R21	Pirelli	3
Tire right front	Winter	Alloy	265/45 R21	Pirelli	4
Tire right rear	Winter	Alloy	265/45 R21	Pirelli	3

A Additional information

No. of keys:	2 🗌 Luxury key	Instruction booklet	(serviceboekje (papier))	Airco works
Interior color:	Black	Maintenance booklet:		Odorless
Upholstery:	Leder			Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	30/05/2023	💟 Display ok

Inspected by: Mik Kieft

5

Last turn mileage(km): 65711

▲ Cleaning

Clean inside (Interior is clean)

Clean outside

Damages

Not acceptable



Front left rim - Scratch



Front left rim - Break



Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Front bumper - Scratch



Front bumper - Scratch



Left sill - Scratch



Rear left door - Paint repair



Rear bumper - Dent



Rear left screen - Paint repair



Tailgate/ lid - Bird droppings



Right outside mirror - Scratch


































































































AUTOFACTOR SOFTWARE FOR AUTOMOTIVE