

Vehicle details

VIN	MPATFS87J KT000853	Brand	ISUZU	Maintenance date	-
Licence Plate	VD-L3-2J	Model	D-Max 1.9 Ext. Cab X-Coun.	Maintenance mileage	-
Registration date	26/11/2019	Year	2019	Exterior Color	White Solid
Odometer	233 139 km	Engine size	1898	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	2	Transmission	Automatic	CO2	-
Doors	2	Gears	-		

Inspection Details

Inspection date	11/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
4x4	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---



Technical Document


User manual	✓
Spare key	✓
Key	✓
Remote key	✓

Tyres



Exterior

1		Part	Door	2		Part	Tailgate / Boot door
		Position	Front left			Position	Back
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Smart Repair



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair