


Vehicle details

VIN	KMHK581GF KU055569	Brand	HYUNDAI	Maintenance date	-
Licence Plate	G5-22-VL	Model	KONA EV Premium 64 kWh	Maintenance mileage	-
Registration date	04/12/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	169 721 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	SUV CrossOver	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	06/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Wireless charger	✗
Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres







Continental 215/55/17 Summer 5.0 mm


Nexen 215/55/17 Summer 5.0 mm

Continental 215/55/17 Summer 5.0 mm


Exterior

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>3</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Number > 2</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Number > 2	Repair mode	Smart Repair
Part	Door																						
Position	Front left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Door																						
Position	Back left																						
Damages	Dented																						
Severity	Number > 2																						
Repair mode	Smart Repair																						
<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
Part	Door																						
Position	Front right																						
Damages	Dent & Chips																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						

Interior damage

<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Severity	-	Repair mode	Smart Repair
Part	Interior tailgate lining										
Position	-										
Damages	Scratched										
Severity	-										
Repair mode	Smart Repair										

Others

<p>1</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Wireless charger</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wireless charger	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Wireless charger										
Position	-										
Damages	Missing										
Severity	-										
Repair mode	For info										