



WAUZZZF32R1050034

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	49,036 km
Manufacturer	Audi	Next maintenance in	11,000 km
Type / Model	Q3	Main inspection (Read from ZBI)	11/2026
Vehicle Identification number	WAUZZZF32R1050034	Power / Engine displacement	110 kW / 1,968 ccm
First registration	17 Nov 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Front bumper	Front bumper - Scratched - Repair and paint
3	Rear bumper	Rear bumper (Stark verkratzt) - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen (Steinschläge) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
	None detectable

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/65 R17 99V	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	225/65 R17 99V	Goodyear	Winter tyres	7mm - 7mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Dec 2024
Protocol number: 37715796
Delivery date: 30 Dec 2024



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	215/65 R17 99V	Hankook	Summer tyres	5mm - 5mm	o.k.	
2	215/65 R17 99V	Hankook	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					08/2027

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Dec 2024
Protocol number: 37715796
Delivery date: 30 Dec 2024



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q3	Mileage (Read)	49,036 km
Vehicle Identification number	WAUZZZF32R1050034	First registration	17 Nov 2023

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was verified during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 30 Dec 2024
Protocol number: 37715796
Delivery date: 30 Dec 2024



Auto Plus



Figure 25: Misc.

Pictures of damage



Damage #2: Front bumper: Front bumper - Scratched - Repair and paint



Damage #2: Front bumper: Front bumper - Scratched - Repair and paint



Damage #3: Rear bumper: Rear bumper (Stark verkratzt) - Deformed - Replace



Damage #3: Rear bumper: Rear bumper (Stark verkratzt) - Deformed - Replace



Damage #3: Rear bumper: Rear bumper (Stark verkratzt) - Deformed - Replace