

Vehicle details

VIN	W0VBD6EN4 KG340451	Brand	OPEL	Maintenance date	-
Licence Plate	28-DM-R8	Model	ASTRA 1.6 CDTI 81KW S/S 120 Jaar Edition 5d	Maintenance mileage	-
Registration date	10/02/2019	Year	2019	Exterior Color	Silver Metallic
Odometer	144 482 km	Engine size	1598	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	10/12/2024	Inspection loc.	LCC3 Alphen Leseman
-----------------	------------	-----------------	---------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✗
Rear parcel shelf	✓

Technical Document






User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/55/16 All seasons 5.0 mm
 Uniroyal 205/55/16 All seasons 6.0 mm

Exterior

<p>1</p>	Part	Alloy wheel 16"	<p>2</p>	Part	Wing
	Position	Front left		Position	Back left
	Damages	Scratched		Damages	Dented
	Severity	-		Severity	Diameter (mm) > 20
	Repair mode	Lumpsum repair		Repair mode	Smart Repair

3		<table border="1"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Back left	Damages	Dented	Severity	-	Repair mode	For info	4		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Step plate																								
Position	Back left																								
Damages	Dented																								
Severity	-																								
Repair mode	For info																								
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
5		<table border="1"> <tr><td>Part</td><td>Spare wheel kit</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Spare wheel kit	Position	-	Damages	Missing	Severity	-	Repair mode	Replace	6		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Spare wheel kit																								
Position	-																								
Damages	Missing																								
Severity	-																								
Repair mode	Replace																								
Part	Door																								
Position	Front right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
7		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Front right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair													
Part	Wing																								
Position	Front right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								