


Vehicle details

VIN	U5YH2519A KL063666	Brand	KIA	Maintenance date	-
Licence Plate	09-DM-S5	Model	CEED 1.6 CRDi DynamicLine 5d	Maintenance mileage	-
Registration date	01/06/2019	Year	2019	Exterior Color	Silver Metallic
Odometer	125 108 km	Engine size	1598	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	30/12/2024	Inspection loc.	Koopman Car Terminal CN
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓




Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓





Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/55/16 Summer 2.0 mm		Pirelli 205/55/16 Summer 3.0 mm	
Pirelli 205/55/16 Summer 7.0 mm		Pirelli 205/55/16 Summer 7.0 mm	

Exterior

1		<table border="1"> <tbody> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </tbody> </table>	Part	Alloy wheel 16"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	2		<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Alloy wheel 16"																								
Position	Front left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Door																								
Position	Front left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
3		<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	4		<table border="1"> <tbody> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </tbody> </table>	Part	Alloy wheel 16"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Door																								
Position	Back right																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Alloy wheel 16"																								
Position	Front right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Lumpsum repair																								