


Vehicle details

VIN	WBA2A5107 0V428133	Brand	BMW	Maintenance date	01/01/1900
Licence Plate	JF-23-6H	Model	2 Serie Active Toure 220iA 5d	Maintenance mileage	-
Registration date	29/02/2016	Year	2016	Exterior Color	Grey Metallic
Odometer	185 164 km	Engine size	1998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	18/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres









Bridgestone 205/55/17 Run-flat 4.0 mm

Bridgestone 205/55/17 Run-flat 4.0 mm





Bridgestone 205/55/17 Run-flat 5.0 mm

Bridgestone 205/55/17 Run-flat 5.0 mm

Exterior

<p>2</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	-	Repair mode	Repair	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 17"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 17"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Bumper																						
Position	Front																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
Part	Alloy wheel 17"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>4</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 17"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 17"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>5</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Front right	Damages	Dent & Chips	Severity	-	Repair mode	Repair
Part	Alloy wheel 17"																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Wing																						
Position	Front right																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Repair																						
<p>9</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Repair	<p>10</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper grille</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Bumper grille	Position	-	Damages	Broken	Severity	-	Repair mode	Replace
Part	Door																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
Part	Bumper grille																						
Position	-																						
Damages	Broken																						
Severity	-																						
Repair mode	Replace																						

Interior damage

<p>1</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	-	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning	<p>6</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Rear parcel shelf</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Not conform</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Rear parcel shelf	Position	-	Damages	Not conform	Severity	-	Repair mode	Replace
Part	Interior cleaning																						
Position	-																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						
Part	Rear parcel shelf																						
Position	-																						
Damages	Not conform																						
Severity	-																						
Repair mode	Replace																						
<p>7</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Severity	-	Repair mode	Replace	<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Sun visor</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Sun visor	Position	Front left	Damages	Broken	Severity	-	Repair mode	Replace
Part	Interior tailgate lining																						
Position	-																						
Damages	Scratched																						
Severity	-																						
Repair mode	Replace																						
Part	Sun visor																						
Position	Front left																						
Damages	Broken																						
Severity	-																						
Repair mode	Replace																						

Comments

Opslagpark : Dekra Ayvens