



**WAUZZZGB6LR040511**

## Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	38,834 km
Manufacturer	Audi	Next maintenance in	20,200 km
Type / Model	A1 Sportback	Main inspection (Report on hand)	04/2025
Vehicle Identification number	WAUZZZGB6LR040511	Power / Engine displacement	110 kW / 1,498 ccm
First registration	5 Mar 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Petrol	Gearbox	Automatic

## Zustandsbericht

### Value reducing factors

No.	Component group	Description
1	Documents	Service book - No evidence
2	Front bumper	Front bumper - Scratch(es) - Smart repair
3	Equipment	Vehicle key (1 von 2 fehlt) - Replace
4	2nd wheel set	Tyres - complete set (Sommerradsatz fehlt) - Replace

### Wear and tear

No.	Component group	Description
		The vehicle shows traces of wear and tear corresponding to its age and purpose

### Missing parts

Missing part
--------------

### Previous damages

No.	Previous damage
1	Rear, Provided by user / customer

### Detected repainting

No.	Location
	None detectable

### Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	185/65 R15 92T	Goodyear	Winter tyres	7mm - 7mm	o.k.	
2	185/65 R15 92T	Goodyear	Winter tyres	8mm - 8mm	o.k.	

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH  
69190 Walldorf

Inspection date: 25 Feb 2025  
**Protocol number: 38566199**  
Delivery date: 25 Feb 2025



## Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					01/2028

The wear and tear condition and possible damages to the tyres are considered in the value.

## Comments

Keine Gewähr auf Vollständigkeit und  
Richtigkeit der angezeigten Ausstattung.  
Techn. Änderungen vorbehalten  
Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.  
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH  
69190 Walldorf

Inspection date: 25 Feb 2025  
**Protocol number: 38566199**  
Delivery date: 25 Feb 2025



---

## Vehicle details

<b>Manufacturer</b>	Audi	<b>Inspection condition</b>	conditional: light/moisture/dirt
<b>Type / Model</b>	A1 Sportback	<b>Mileage (Read)</b>	38,834 km
<b>Vehicle Identification number</b>	WAUZZZGB6LR040511	<b>First registration</b>	5 Mar 2020

**Vehicle identification:**

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

**Inspection conditions:**

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

**General condition:**

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior





Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH  
69190 Walldorf

Inspection date: 25 Feb 2025  
**Protocol number: 38566199**  
Delivery date: 25 Feb 2025



## Pictures of damage



**Damage #2:** Front bumper: Front bumper - Scratch(es) - Smart repair



**Damage #2:** Front bumper: Front bumper - Scratch(es) - Smart repair