



WAUZZZFZ9RP014956

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	22,319 km
Manufacturer	Audi	Next maintenance in	8 Monat(e)
Type / Model	Q4 40 e-tron	Main inspection (Read from ZBI)	10/2026
Vehicle Identification number	WAUZZZFZ9RP014956	Power / Engine displacement	70 kW
First registration	5 Oct 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book - No evidence
2	Door - front right side	Door - Scratch(es) - Cover / polish
3	Interior	Interior (Tierhaare) - Clean
4	Door - rear left side	Door - dent(s) - Smooth repair work
5	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
6	Wing mirror - right side	Mirror glass - Damaged - Replace
7	Front bumper	Air-inlet grille - Damaged - Replace
8	Door - rear right side	Door - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Door - front left side

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Feb 2025
Protocol number: 38543677
Delivery date: 24 Feb 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101H	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	235/55 R19 101H	Pirelli	Winter tyres	7mm - 7mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/50 R19 103T	Bridgestone	Summer tyres	4mm - 4mm	o.k.	
2	255/50 R19 103T	Bridgestone	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Feb 2025
Protocol number: 38543677
Delivery date: 24 Feb 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q4 40 e-tron	Mileage (Read)	22,319 km
Vehicle Identification number	WAUZZZFZ9RP014956	First registration	5 Oct 2023

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Feb 2025
Protocol number: 38543677
Delivery date: 24 Feb 2025



Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Feb 2025
Protocol number: 38543677
Delivery date: 24 Feb 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #2: Door - front right side: Door - Scratch(es) - Cover / polish




Damage #2: Door - front right side: Door - Scratch(es) - Cove...
polish



Damage #2: Door - front right side: Door - Scratch(es) - Cover /
polish



Damage #3: Interior: Interior (Tierhaare) - Clean



Damage #3: Interior: Interior (Tierhaare) - Clean



Damage #4: Door - rear left side: Door - dent(s) - Smooth rep...
work



Damage #4: Door - rear left side: Door - dent(s) - Smooth repair work



Damage #5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage #5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage #6: Wing mirror - right side: Mirror glass - Damaged - Replace



Damage #7: Front bumper: Air-inlet grille - Damaged - Replace



Damage #7: Front bumper: Air-inlet grille - Damaged - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Feb 2025
Protocol number: 38543677
Delivery date: 24 Feb 2025



Auto Plus



Damage #8: Door - rear right side: Door - dent(s) - Repair and paint



Damage #8: Door - rear right side: Door - dent(s) - Repair and paint