



**WAUZZZGY7MA068113**

## Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	43,727 km
Manufacturer	Audi	Next maintenance in	16,300 km
Type / Model	A3 Sportback	Main inspection (Report not on hand)	07/2026
Vehicle Identification number	WAUZZZGY7MA068113	Power / Engine displacement	81 kW / 999 ccm
First registration	8 Jan 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Petrol	Gearbox	Manual

## Zustandsbericht

### Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Rear bumper	Rear bumper - Scratched - Repair and paint
5	Door - rear left side	Door - Scratched - Repair and paint
6	Door - rear right side	Door - Scratched - Repair and paint
7	Front bumper	Front bumper - Scratched - Repair and paint
8	Side panel - rear right side	Side panel - Scratched - Repair and paint

### Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

### Missing parts

Missing part

### Previous damages

No.	Previous damage
1	Front, Provided by user / customer

### Detected repainting

No.	Location
1	Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 11 Mar 2025  
**Protocol number: 38790512**  
Delivery date: 11 Mar 2025



Auto Plus

## Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91T	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	205/55 R16 91T	Pirelli	Winter tyres	6mm - 6mm	o.k.	

## Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91V	Nexen	Summer tyres	6mm - 6mm	o.k.	
2	205/55 R16 91V	Nexen	Summer tyres	6mm - 6mm	o.k.	

## Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					11/2024

The wear and tear condition and possible damages to the tyres are considered in the value.

## Comments

Keine Gewähr auf Vollständigkeit und  
Richtigkeit der angezeigten Ausstattung.  
Techn. Änderungen vorbehalten  
Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.  
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH  
69190 Walldorf

Inspection date: 11 Mar 2025  
**Protocol number: 38790512**  
Delivery date: 11 Mar 2025



---

## Vehicle details

<b>Manufacturer</b>	Audi	<b>Inspection condition</b>	Sufficient
<b>Type / Model</b>	A3 Sportback	<b>Mileage (Read)</b>	43,727 km
<b>Vehicle Identification number</b>	WAUZZZGY7MA068113	<b>First registration</b>	8 Jan 2021

**Vehicle identification:**

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

**Inspection conditions:**

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

**General condition:**

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



**Figure 1:** Diagonal front




**Figure 2:** Diagonal front



**Figure 3:** Diagonal rear



**Figure 4:** Diagonal rear



**Figure 5:** Interior



**Figure 6:** Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 11 Mar 2025  
**Protocol number: 38790512**  
Delivery date: 11 Mar 2025



Figure 19: Misc.




Figure 20: Misc.

## Pictures of damage



**Damage #4:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #4:** Rear bumper: Rear bumper - Scratched - Repair and paint




**Damage #4:** Rear bumper: Rear bumper - Scratched - Repair and paint



**Damage #5:** Door - rear left side: Door - Scratched - Repair a...



**Damage #5:** Door - rear left side: Door - Scratched - Repair and paint



**Damage #5:** Door - rear left side: Door - Scratched - Repair a...





**Damage #6:** Door - rear right side: Door - Scratched - Repair and paint



**Damage #6:** Door - rear right side: Door - Scratched - Repair and paint



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #7:** Front bumper: Front bumper - Scratched - Repair and paint



**Damage #8:** Side panel - rear right side: Side panel - Scratch... - Repair and paint



**Damage #8:** Side panel - rear right side: Side panel - Scratched - Repair and paint



**Damage #8:** Side panel - rear right side: Side panel - Scratch... - Repair and paint



**Damage #8:** Side panel - rear right side: Side panel - Scratched - Repair and paint