

WAUZZZFZ2RP087893

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	11,494 km
Manufacturer	Audi	Next maintenance in	16 Monat(e)
Type / Model	Q4 45 e-tron	Main inspection (Read from ZBI)	08/2027
Vehicle Identification number	WAUZZZFZ2RP087893	Power / Engine displacement	89 kW
First registration	7 Aug 2024	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Interior	Office bag (Fehlt) - Replace
2	Front bumper	Front bumper - Scratched - Paint
3	Door - rear right side	Door - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	255/50 R19 103H	Pirelli	Winter tyres	8mm	o.k.	
	235/55 R19 101H	Pirelli	Winter tyres	8mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 17 Mar 2025
Protocol number: 38890309
Delivery date: 17 Mar 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101T	Bridgestone	Summer tyres	6mm - 6mm	o.k.	
2	255/50 R19 103T	Bridgestone	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 17 Mar 2025
Protocol number: 38890309
Delivery date: 17 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	Q4 45 e-tron	Mileage (Read)	11,494 km
Vehicle Identification number	WAUZZZFZ2RP087893	First registration	7 Aug 2024

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 17 Mar 2025
Protocol number: 38890309
Delivery date: 17 Mar 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 17 Mar 2025
Protocol number: 38890309
Delivery date: 17 Mar 2025



Auto Plus



Figure 25: Misc.



Figure 26: Misc.

Pictures of damage



Damage #2: Front bumper: Front bumper - Scratched - Paint



Damage #2: Front bumper: Front bumper - Scratched - Paint



Damage #2: Front bumper: Front bumper - Scratched - Paint



Damage #3: Door - rear right side: Door - Scratched - Paint



Damage #3: Door - rear right side: Door - Scratched - Paint